

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }
Gogebic County } ss.

For corners in
Gogebic
(County)

Located In:

Corner Code ##

Received for record the

4th day of October

A. D. 1993 at 2:50 o'clock

P m., and recorded in

Liber 4 of CORNERS

on page 263 287

Betty Saar's Deputy
Register of Deeds

Register of Deeds Stamp & File Number

1. Public Land Survey

T 45N R 41W

K-L, 3

T R

001

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Gary L. Pisoni, in a field survey on May 26, 1992, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by A. Merryweather, U.S. Deputy Surveyor, on June 8, 1852.

Original corner: 9" Cedar as corner tree

Original bearing tree:

Hemlock

18"

N 86°W

9 links (5.94 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. H.S. Tuttle R.L.S. 1777, placed a 2" diameter iron pipe on the West shore of Beaton's Lake and then he surveyed lots in Section 1 along the West shore of Beaton's Lake. I used H.S. Tuttle's iron pipe as a Witness Corner because the true location of the Meander Corner is 39.0 feet further East. I accepted the iron pipe as the best available evidence for restoring the corner position.

PEER GROUP APPROVED

Richard P. Weale 4/7/94
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Into the center of Tuttle's 2" diameter iron pipe I drove a 3/4" diameter by 3 foot long solid aluminum marsh rod with a 3" diameter cast aluminum cap, stamped to read: T45N, R41W, S-1, S-12, W.C., M.C., 1992, S 89°35'49"E, 39.0 feet, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Red Maple	6"	N 17°W	6.04 feet
Cedar	12"	N 22°E	25.66 feet
Red Maple	14"	S 05°E	10.80 feet
Steel Sign Post		West	1.10 feet

Signed by Gary L. Pisoni

Date Sept 29, 1993

Surveyor's Michigan License No. 27457

