

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic

(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 41W

H, I-11b

T

R

003

T

R

T

R

2. Property Controlling
in Section

PEER GROUP

Approved

3. Miscellaneous
Property in Sec.

Richard L. Pisoni

5/25/94

Register's Office } ss.
Gogebic County }

Received for record the

12 day of June

A. D. 1994 at 1:45 o'clock

P m., and recorded in

Liber 5 of CORNERS

on page 68

Richard J. Brown

Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

West Meander Corner between Sections 27 and 34

I, Gary L. Pisoni, in a field survey on December 18, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Algernon Merryweather, U.S. Deputy Surveyor on June 14, 1852.

Original corner: 4" Hemlock corner tree

Original Bearing Tree:

Hemlock 12" N 08°W 5 links (3.30 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence remains of original corner or bearing tree. Corner position found marked by a 1" X 30" iron pipe located on the West shore of Clearwater Lake. Iron pipe set by unknown person. I accept the iron pipe as the best available evidence for restoring the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron pipe with a 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T45N, R41W, S-27, S-34, M.C., 1993, RLS- 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Red Maple	10"	S 49°W	16.70 feet (Bottom Blaze no BT signs)
Red Maple	18"	N 57°W	52.33 feet (No Blazes, no BT signs)
White Pine	18"	N 20°W	25.15 feet (No Blazes, no BT signs)
Steel Sign Post		West	1.02 feet

Signed by Gary L. Pisoni

Date 4-1-94

Surveyor's Michigan License No. 27457

