LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Register'	s Office	SS
	Register's Gogebic	County	

Received for record the

For c	orners in					/ 5		JUNK		
	Gogebic	Located	In:	Corner Code ##		A. D. 19	94 at 1:			
	(County)						m., and			
1. P	ublic Land Survey	T _45	NR 41W	H,I-lla		Liber		CORNERS		
			R	004	_				.,	
	•	Ţ	_ R		-	en page				
2 0	roperty Controlling	REER GRO)UP	Approved	-	_AIC	Card.1.18	er of Deed		
	Section	s At	OB A	-tikhi o 100	_		negan	si or Door	Ŋ	
	Niscellaneous	Richard	2RJ	F/25/04	Re	gister of De	eeds Stamp	& File Numl	ber	
P	roperty in Sec.	S1_	_ H							
	4 81	Decorded Diet				•				
	ot No , rivate Claims					· A B	C D E F	GHIJ	K L	M
J, F	mate Claims					2 6-	_ {	3		
E	ast Meander co	rner between S	ections 27	7 and 34.		3			-	\vdash
			_	110	0.7	4		1011-	+-1	2
1,	Gary L. Pisoni	, in a field survey (onDecem	nber 18 , 19 of 1970, the corner points	93 montioned	5		 	+	H
go ne in line	reby certify that under ress. 1 and 2 above were	equirements of P.A. 74, in conformance with	regulations and	i rules therefore as req	uired in the	6 18	1716	1514-	1-1	3—
curre	nt manual of survey ins	tructions of the United	i States Departr	ment of the Interior, Bur-	eau of Land	7			+	H
Mana _s	gement or by a decree o were in conformance v	or a Court of Law and/or with the rules of the Mir	r that the corner chigan Board of	points mentioned in line Land Surveyors or by a	Decree of a	8 19	2021 	22 23-	2	4
Court	of Law; established,	re-established, mon	umented, re-m	onumented, recovered	, found as	10 _ 30_				
•	ssed below:					11	29	21 26	1	ارا
NOTE	: Not more than 4 on this certificate		ame town and	d range, may be reco	raea	1231				
	Off this Certificati	G.				13		J. J.		
Ą. E	Description of origina	il monument and acc	cessories and	or subsequent resto	ration:					
	Original corn Original Bear	er: 12" Hemlo	6"	non Merryweathe tree North	9 links					
						-				
		•								
8 . C	Description of corner	evidence found and	d/or method a	pplied in restoring or	reestablishing	corner:				
	marked by a 1 Lake. Iron p	1/2" iron pipe pipe set by unk	and angle known pers	er or bearing t iron located c on. I accept t oring the corne	on the East the iron pi	shore one a	of Clearwa	ater		
					•					
						•				
						;				
C . D	escription of monum	nent for corner and	accessories e	stablished to perpetu	ate locating th	ne position	of the corne	r:		
	Replaced 1/2" pipe monument S-34, 1991, RI	pipe and angle with a 3" cast LS- 27457 from	e iron with aluminum which I es	h a 2" diameter cap, stamped t stablished the	by 30" lo	ng split 45N, R41	base alu. W, M.C.,	uminum S-27,		
	•	ents taken to a emlock	16"	s 10 ^G E	5.22	feet (No	blazes o	or signs	on	вт
		edar	11"	s 45 ⁰ E	23,44	feet (No	blazes o	or signs	on	BT
		emlock	16"	N 42 ^O E	26.27	feet (No	blazes o	or signs	on	BT
		ngar Maple	10"	N 11 ⁰ W S 84 ⁰ E	24.77	feet (No	blaces to	Mr.signs	on	вт
	St	ceel Sign Post		5 84 E	1.22	ree c	ar . a. l	TIGA SA		

U.S.F.S. #V-16,17

Surveyor's Michigan License No. 27457

67

PISONI
LAND
SURVEYOR
FORM APPROVED BY MICROAN STATE BOARD OF LAND SURVEYORS, AM. 20, 19
REVISED MAY 14, 19
REVISED MAY 14, 19
REVISED MAY 14, 19