LAND	CORNER	RECO	RDATIC	N CEF	RTIFI	CATE
Filing	Requirem	ent of	Act 74	Mich	РΔ	1970

	Register's Office Ss.
	Received for record the
	A. D. 19.93 at 9:15 o'clock A. m., and recorded in
,	Liber 4 Of CORNERS
_	Betty San Deputy Register of Deeds
cto	or of Deads Stamp & File Number

ΓŲ	Contigua III			
Gogebic (County)		Located In:	Corner Code ##	
1.	Public Land Survey	T 45N R 41W	E-12,13	
		T R	(006)	
		T R		
		T R	· · · · · · · · · · · · · · · · · · ·	
2.	Property Controlling	S		
	in Section	S R		
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		

I. Gary L. Pisoni, in a field survey on September 15, 19 92.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by A. Merryweather, U.S. Deputy Surveyor on June 18, 1852.

Original corner: Corner Tree - 8" Cedar

___ , Recorded Plat _

Original bearing trees:

5. Private Claims _

Balsam

6"

N 79°W

3 links (1.98 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. At the corner position, found an 1 1/4" dia. Iron pipe as shown on old survey maps from surveys in Sections 32 and 33. I accepted the iron pipe as the best available evidence for restoring the corner position.

Monument is 11 feet from waters edge.

Reclard L. Weakn 1/20/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I replaced the iron pipe and set a 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T45N, R41W, S-32, S-33, M.C., 1992, RLS 27457; from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Sugar Maple 10" N 370W 29.55 feet

 Sugar Maple
 10"
 N 37°W
 29.55 feet

 Sugar Maple
 12"
 S 11°E
 6.08 feet

 Sugar Maple
 8"
 N 83°W
 51.25 feet

 SW corner of storage shed N 64°E
 9.1 feet

No B.T. signs or upper blazes on bearing trees.

Signed by Aary L. Knows
Surveyor's Michigan License No. 27457

_____ Date __

GARY L.
PISONI
LAND
SURVEYOR
No.
27457

D SURVEYDAS, JAN. 21

U.S.F.S. #Y,Z-9