			Register's Office
	LAND CORN	IER RECORDATION CERTIFIC	
	Filing Requi	rement of Act 74, Mich. P.A.	1970 Received to
For corners in		•	day of November
Gogebic (County)	Located In:	Corner Code ##	74 W. 1972 21 /./5 o'clock
1. Public Land Survey S	Section 7 (45N R 43W. T 45N. R 44W.	· · · · · · · · · · · · · · · · · · ·	Liber 5 of COANERS page 305
2. Property Controlling in Section	T R S T R S T R		Register of Deeds
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number
5. Private Claims	on to Sections 12 and 7, T45N,		A B C D E F G H 1 J K L N
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance wit	quirements of P.A. 74, Michigan P.J o conformance with regulations a uctions of the United States Depa a Court of Law and/or that the con- th the rules of the Michigan Board	November 3 , 19 94 A. of 1970, the corner points mentione and rules therefore as required in the artment of the Interior, Bureau of Larner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of e-monumented, recovered, found	ed he nd 7 3-16 15 -14 3-15 15 15 15 15 15 15 15 15 15 15 15 15 1
NOTE: Not more than 4 coon this certificate.	orners, all in the same town	and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original r	monument and accessories a	nd/or subsequent restoration:	
- In 1847 John Burt	set the meander corner being a	14" tamarack from which a 10" c	edar bears N75°W - 5 links.
		14)	in Liber 1 Page 70 and 80 Corner consisted

In 1966 Don Lappata, R.L.S. 12858 reestablished the corner position as recorded in Liber 1, Page 79 and 80. Corner consisted of a 3" brass capped pipe stamped: T45N, R44W, R43W, M.C., S-12, S-7, S-13, 1966, R.L.S. 12585, from which a:

8" cedar bears S88'E - 13.7 feet 9" cedar - S01'W - 9.4 feet 13" Y. birch - S60'W - 19.7 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 3" brass capped pipe as described above in Section "A" and updated this position to state and county specifications as noted below. Above bearing trees are all dead or decayed.

Act 74 record on file with Register of Deeds office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 3" brass capped pipe as described above in Section "A". I established the following bearing trees and/or reference object:

14" Y. birch - S64°E - 79.25 feet 10" Y. birch - S35°W - 69.79 feet 3" B. spruce - N76°W - 87.37 feet Sign post - S74°W - 2.11 feet

redurati Dean 1116/95

1 / 00

JOHN R. GARSKE LAND SURVEYOR No. 28410

Signed by

Surveyor's Michigan License No.

28410

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

REVISED MAY 14, 1975 REVISED JAN., 1982