

SURVEY &
REMONUMENTATION

AUG 08 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic

(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 46W

BC-1-2

T _____ R _____

T _____ R _____

T _____ R _____

009

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Mile Corner No. 1; Mich.---Wisc. State Line

Richard L. Drahn in a field survey on July 10, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847 at a 9" Hemlock. Original B.T.s
--- Tamarack 20" S.49 W. 25 links (16.50') --- Cedar 10" N.25 W. 7 links
(4.62') ---

Corner restored in the center of a decayed Hemlock stump by Earl Harrington
in 1928 at the bearing and distance from the scribed remains of the two
original B.T.s. He set a standard State Line concrete, brass capped monument
and two new B.T.s. --- Cedar 8" N.50 E. 25.4' --- Cedar 8" S.06 W. 10.6' ---

Daniel K. Pleoger, Wisc. S-1537 recovered the 1928 monument but no 1847 or
1928 B.T.s. He established the following new B.T.s, on 8/31/88:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

--- 8" (9") Hemlock N.50 E. (N.48 E.) 26.91' (26.89') --- 9" Cedar S.37 E.
(S.39 E.) 22.51' (22.44') --- 6" Black Spruce S.45 W. (S.46 W.) 9.14' (9.11')
--- 9" Hemlock S.70 W. (S.68 W.) 24.69' (24.82') ---.

I recovered the standard brass capped 1928 monument as described above and
the badly decayed remains of the two 1928 Cedar B.T.s. No evidence remains
of the 1847 B.T.s.

Recovered Daniel Pleoger's 1988 B.T.s as shown in parentheses above.

Research Form on file with Gogebic County records.

Daniel Pleoger's Corner Certificate filed with Iron County, Wisc. records
on 3/7/89 at 12:00 PM.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following
new bearing object:

6' Steel sign rail N.37 W. 2.22 ft.

PEER GROUP APPROVED

Richard L. Drahn 7/15/97
COUNTY REPRESENTATIVE

Signed by Richard L. Drahn

Date July 13, 1997

Surveyor's Michigan License No. 21564

USFS AB-3-4

166

Register's Office }
Gogebic County } ss.

Received for record the

16TH day of JULY

A. D. 1997 at 1:40 o'clock

P m., and recorded in

Lib. 6 of CORNERS

on page 166

Colleen M. Kibak
Deputy Register of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11								
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

