SECTION

| F | EAND Filin | g Requirement of | PRDATION CERTIF Act 74, Mich. P.A. | FICATE "S | egebic Cour | ice Se. | |
|--|--|---|---|--|--|---|-------------------|
| For corners in | | | 1 | | Recei | ved for record | I th |
| <u>Gogebic</u> (County) | Located In: | Corner Code # | ! | | 12.74 | day of MAY | |
| | - 4631- | 40 | | A. | D. 19 <u>99.</u> | at 10:45 o'c | clock |
| 1. Public Land Survey | T <u>46NR_</u> TR_ | 43W <u>J-</u> | · <u>7</u> | - | A m | , and records | d in |
| | TR_ | | | | ber 7 | OI CORN | <u> </u> |
| 2. Property Controlling | TR_ S TR_ | | | 4.) | page /Z | | |
| in Section | S TR_ | | | 74 | mena Col | | 44 |
| Miscellaneous Property in Sec. | S TR_ | | | , | | Register of De | 60 de |
| Property in Sec. | s | | | Registe | r of Deeds St | amp & File Nur | mber |
| 4 Lot No December | la d Mist | | | | | | |
| 4. Lot No , Record 5. Private Claims | ed Plat | | | A B C | DEF | зні јк | L |
| | | , | | 2 6 | | | |
| Quarter Corner 14 | | | | 3 | | | |
| Richard L. Drahn | in a field survey on _ | May 10, 19 99 | do hereby state that unde | er 4 - 7 | _ | | _ 12- |
| conformance with regulations and a | P.A. of 1970, the corner ules therefore as required | r points mentioned in fir I in the current manual o | nes 1 and 2 above were i | in 5 | | | _Ī. |
| Oraced States Department of the Int | lerior. Sureau of Land Ma | magement or by a decre | e of a Court of Low and la | se | -1716 | | 13- |
| that the corner points mentioned in Board of Land Surveyors or by a | Decree of a Court of | Law; established, re- | n the rules of the Michiga ⊵stablished, monumented | n 7 | | | |
| recovered, iourid as expressed belo | w: | | | 8 19 | -20-21- | 2223 | 24- |
| NOTE: Not more than 2 come | rs, all in the same town | and range, may be re | ecorded | 9 | | - | _ |
| on this certificate. | | | | 10 30 | -2 ['] 92 ['] 8 | 2726 | 2 ¹ 5~ |
| | | | | 11 | | | + |
| | | | | 12 31 | -3233 | 3435 | —36- |
| A. Description of original mont | iment and accessorie | s and/or subsequent | restoration: | 13 | <u></u> | —————————————————————————————————————— | |
| Corner establishe Tamarack S.89 E. | d by Austin 53 links (34 | Burt on 7/1 | 17/1851. Or 6" Tamarack 1 | iginal B. N.33 W. 9 | T.s O links | 6" (59.40!) | |
| Corner restored be of the SE B.T., a to recovered sect stamped aluminum 8.74' 7" Blace | y Richard L. matural feation corners. cap and the K Spruce S.0 | Drahn, RLS ature tie we He set a following r 3 E. 14.62 | S 21564 on 16 est, and ret; 3/4" X 10' and sew B.T.s: | 0/22/84 f racement aluminum 6" Bla ck Spruce | rom the measure rod witl ck Sprud S.83 W | remains ment E & n a 3¼" | W |
| Corner recorded i | n Gogebic Co | ounty Liber | 2, Page 653 | on 12/10 | /84. | | |
| B. Description of corner evider | nce found and/or meth | nod applied in restori | ng or reestablishing co | orner: | | | |
| Recovered the mon | ument as des | cribed and | the bearing | trees as | follows | 3: | |
| o Blac | k Spruce k Spruce | N.63 E. | 8.74' (ı | new nail) | | | |
| 7" Blac | k Spruce | S.05 E. S.84 W. | 14.58' 10.25' (r | new nai1) | | | |
| 6' Stee | 1 sign rail | s.84 W. | 2.04 | | | | |
| The SE B.T. is no | w a very bad | ily decayed | Tamarack stu | ımp. | | | |
| Corner research o | n file with | Gogebic Cou | inty records. | • | | | |
| C. Description of monument for | corner and accessorie | es established to per | petuate locating the p | osition of the co | mer: | | |
| New bearing | tree referen | .ced: | | | | I ALCOHOL | • |
| 7" Blac | k Spruce | N.13 W. | 21.03 | į | RI L. | CHARD DRAHN LAND | |
| ٨ | ſ | Victoral | 1 2 2 5/11 1 2 2 2 5/11 | 1/98 | , SU | RVEYOR No. 21564 | |
| Signed by Richard | L. Deal | 2 | Date <u>M</u> a | y 11, 199 | ALC: NO. | WHO SHEET | |
| Surveyor's Michigan License No. | 21564 | | | | | | |
| USFS N-19 | | | | | | | |