Register's Uffice LAND CORNER RECORDATION CERTIFICATE Segebic County Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Received for record the 26 M day of MAY Gogebic Located In: Corner Code # A. D. 15 00 at 10:40 o'clock A m., and recorded in SURVEY & T46 N R44 W. REMONUMENTATION 1. Public Land Survey Liber 7 OF CORNERS # page 297 JAN 05 2001 2. Property Controlling Register of in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 2 Section Corner 20, 21, 28 & 29; T.46 N., R.44 W. 3 Richard L. Drahn \_, in a field survey on April 10, 2000 4 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in 5 lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner 7 points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt on 8/13/1851. Original bearing trees: Hemlock 34" S.74° E. 13 links (8.58')14" N.54° W. 54 links (35.64')Corner restored by Richard L. Drahn, RLS 21564 on 11/7/83 from the remains of the original Hemlock B.T. and from recovered line trees north and east to recovered line trees. He set a 2" X 30" aluminum pipe with a 3 1/4" stamped aluminum cap and the following B.T.s: White Ash 8" N.88° W. 21.93' 10" **Red Maple** N.52° E. 11.16 11" S.10° E. Red Maple 7.62 S.02° E. Steel sign rail 6' 2.38 Corner recorded in Gogebic County Liber 2, Page 551 on 1/26/84. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner research on file with Gogebic County records.

Recovered the monument as described and the bearing trees as follows:

White Ash

10"

N.88° W.

21.91

(new nail)

Red Maple

13'

N.53° E.

Red Maple

14'

S.12° E.

11.02' (new nail) 7.54 (new nail)

Steel sign rail

6

S.03° E.

2.36

A very large Hemlock, decayed to below ground line still remains identifiable bearing S.74° E., 8.6'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing tree established\*

Sugar Maple

N.19° W.

15.86

Date <u>May 2, 2000</u>

Surveyor's Michigan License No.\_\_\_ 21564 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

OT MICHIG

RICHARD L. DRAHN LAND SURVEYOR No. 21564

USFS R-9