

SURVEY &  
REMONUMENTATION

SEP 08 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office } ss.  
Gogebic County }

For corners in

Gogebic

(County)

Located In:

Corner Code #

1. Public Land Survey

T46NR 45W

G-7

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

S.C. comm. to sec's. 15, 16, 21 & 22

I, John P. Goss, in a field survey on March 16, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on July 19, 1851. Set post.

Original bearing trees: Hemlock 7" S 52° W 30 links

Y. Birch 14" N 35° E 15 links.

In April 1960, Carl Koistenen of MDOT found a 1½" iron pipe with brass cap. He established the following witnesses.

4" Maple S 45° W 06.47'

8" Maple North 08.08'

4" Maple S 65° E 13.31'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found C. Koistenen called for iron pipe with brass cap. Also blue painted lines North, South and West. Corner location sign on three (3) trees.

A 1½" iron pipe with 2" brass cap is located at 1/16 corner to West of section corner. Location signs are dated 1982 and 1991.

No evidence of the original bearing trees.

I accepted this as best position for section corner.

I updated the corner monument and accessories as noted below to state and county specification.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the found 1½" O.D. iron pipe with 2" brass cap which reads:

Northern Paper Mill; 15, 16, 21, & 22. I established the following reference objects.

9" Maple S 50° W 6.45'

11" Maple N 08° E 8.08'

7" Maple S 02° E 12.23'

9" Maple Due West 9.04'

7' metal post  
and sign Due East 1.85' (to face)

(All measurements to nail in side of tree)

Signed by John P. Goss

Surveyor's Michigan License No. 23509

Date March 16, 1998

Fed. No. N-13

Register of Deeds Stamp & File Number

Received for record the  
14<sup>th</sup> day of MAY

A. D. 1998 at 3:10 o'clock

P m., and recorded in

Liber 6 of CORNERS

on page 358

Ramona Collins Deputy  
Register of Deeds