	negia Goge!				<b>i.</b>			
For corners in			Recei	ved fo	or 1000		)	
Gogehic Located In: Corner Code ##	A D	. 19		-	1.50		•	
(Counity)		حد			reco			
1. Public Land Survey  T 47N R 47W H-I-13 610  T R	Liber		5		e Co.			
T R HI-1 001	Z.	Age	28	6 mg		DO DE	T 14	
2. Property Controlling S T R	TANG	II ISA		Roga	MAN CASTA	Pund	T	
in Section S T R								
3. Miscellaneous S T R Regis	ster (	of D	eeds	Stamp	p & File	e Numi	oer	
Property in Sec. S I								_
4. Lot No, Recorded Plat	A	В	c 0	E F	G H	ل ایم	K L	м
5. Private Claims	2	Ţ		T	TŢ'	Ţ	ŢŢ	٦
Meander corner common to Section 34, T47N, R47W and Section 3, T46N, R47W	3			Ti				
•	4	Ţ		ŢŢ	10			$\Box$
ı, John R. Garske , in a field survey on April 20 , 19 95 ,	5	Ĺ	_ i_	Li	Ĭ		Ιï	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	6	18		16-	15.	14-	13	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	7	Ĭ	LÏ.	<u>lï</u>	1	11	1 1	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	8	19	20-	21-		23		Ц
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	9	Ĺ						
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	10	30	29	28	27	26	25	
·	11	1		14		11	$\perp$	_
	12	31		33-		35	36	;
·	13	1						لــ
A. Description of original monument and accessories and/or subsequent restoration:								
- On 1847, William A. Burt set a Y. birch post from which a 10" fir bears S60°E, 80 links a	and ar	ı 8"	fir - N	167°E,	, 77 lin	ıks.		
· · · · · · · · · · · · · · · · · · ·								
B. Description of corner evidence found and/or method applied in restoring or reestablishing c	corne	r:						

Record research on file with Register of Deeds.

information exists.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 2 1/2" diameter x 30" long aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T47N, R47W, T46N; M.C.; S-34; S-3; 1995; R.L.S. 28410, from which I established the following bearing trees and/or reference object: OF MICE

and 3 until intersecting the bank of the Montreal River. I believe that this is the only possible location for this corner as no other

7" spruce - N83°E - 15.78 feet 10" spruce - S43°W - 5.83 feet 10" spruce - N24°W - 4.53 feet

6' steel rail with sign - S35°E - 1.37 feet Edge of river - Due West - 6.5 feet

Corner is set in 60# of concrete

≣igned by Eurveyor's Michigan License No.

LAND SURVEYOR No. 28410

JOHN R.

GARSKE

LAND

REVISED MAY 14, 1975 REVISED JAN., 1983

Fed. No. Z-16-17

2 21