

**SURVEY &
REMONUMENTATION**

AUG 08 1997

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

Register's Office }
Gogebic County } ss.

Received for record the
16th day of JULY

A. D. 1997 at 1:40 o'clock

P. m., and recorded in

Lib. 1 of CORNERS

on page 170

Colleen M. Kibak

Deputy Register of Deeds

Register of Deeds Stamp & File Number

For corners in

Gogebic
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 46N R 47W

LM-12-13

T R

T R

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

002

4. Lot No. , Recorded Plat

5. Private Claims

Mile Corner No. 0; Mich.---Wisc. State Line

Richard L. Drahn in a field survey on July 9, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- W. Pine 24" N.74-45 E. 142 links (93.72') --- Hemlock 24" S.13-30 E. 154 links (101.64') --- W. Pine 26" S.64-15 W. 120 links (79.20') ---

Corner restored by Earl Harrington in 1928 from the stump remains of the two W. Pine B.T.s. He set a standard State Line concrete, brass capped monument and established two new B.T.s. --- Y. Birch 16" S.26-40 E. 113.5' --- Y. Birch 16" S.45-20 E. 190.7' ---

Daniel K. Pleoger, Wisc. S-1537, recovered the concrete monument and scribed W. Pine B.T. stub at N.74-45 E. on 8/31/88. He also recovered the decayed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

remains of the two 1928 B.T.s. He established the following new bearing objects: --- 1/2 X 24" rerod N.45 W. 45.00' --- 1/2 X 24" rerod North 45.00' --- 1/2 X 24" rerod East 50.00' --- 9" Balsam S.80E. 77.45'.---

I recovered the standard brass capped concrete monument as described in Earl Harrington's notes. His B.T. at S.45-20 E. is now a badly decayed Y. Birch. No evidence remains of his S.26-40 E. B.T.

Only a large, broken W. Pine stub (no scribing) at N.74-45 E. remains of the original 1847 B.T.s.

Recovered Daniel Pleogers 1988 bearing objects as described on his Land Corner Certificate filed with Iron County on 3/7/89 at 12:00 PM.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Research Form on file with Gogebic County records.

From the above described concrete monument I established the following new bearing object:

6' Steel sign rail N.49 E. 2.65'

PEER GROUP APPROVED

Richard L. Drahn 7/15/97
COUNTY REPRESENTATIVE

Signed by Richard L. Drahn

Date July 13, 1997

Surveyor's Michigan License No. 21564

USFS XY-24-25

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

AUG 8 1997

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

