

SURVEY & REMONUMENTATION

JAN 05 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office
Gogebic County

For corners in
Gogebic
(County)

Located in: Corner Code #

1. Public Land Survey T46NR47W
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

R&D

L-M-11
K-E-11

010

Received for record the
2ND day of JUNE
A. D. 1900 at 10:20 o'clock
A. m., and recorded in
Book 7 of CORNERS
on page 360
Cheryl Ruggie, Reg.
Register of Deeds

Register of Deeds Stamp & File
Number

4. Lot No. , Recorded Plat
5. Private Claims
Meander Corner common to Sections 25 and 36.

I, John R. Garske, in a field survey on May 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and / or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and / or subsequent restoration:

Original survey by William Ives, Sept. 1848.

Original Corner: A wood post was set at the intersection of the section line common to Sections 25 and 36 and the Montreal River.

Original Bearing Trees: 8" Balsam N 30° E 45 Links
6" Spruce S 77° E 8 Links

B. Description of corner evidence found and / or method applied in restoring or re-establishing corner:

No corner evidence was found. We used the G.L.O. distance to set the meander corner along the section line by extending the centerline of an old trail which runs down the section line from the section corner on the range line.

Record research on file.
(See sketch on back)

DEED GROUP APPROVED
Richard R. Pedra 5/24/00
COUNTY DEEDS & RECORDS

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3" x 30" aluminum Bernsten monument as a witness to the actual meander corner which fell in the river. I established the following witnesses:

Steel Sign Post	N 62° W	0.92 Feet
6" Black Cherry	S 11° W	9.07 Feet
6" Balsam	N 88° E	16.33 Feet
12" Twin Yellow Birch	N 25° E	16.89 Feet

Signed by John R. Garske

Date 5/24/00


Surveyor's Michigan License No. 28410
FB # 251, page 26-27



LM-11

Meander Corner common to Sections 25 & 36,
T 46 N, R 47 W.

SURVEY &
REMONUMENTATION
JAN 05 2001
SECTION



Not to scale

