SURVEY & REMONUMENTATION

SEP 0 8 1998

3EP # 8 1998				Register's Offic	(9
	LAND CO	RNER RECORDATI	ON CERTIFICATE	Gogebie : bunt	v S8.
SECTION		uirement of Act 7		Receive	d for record the
For corners in	•				ed for record the
Gogebic (County)	Located In:	Corner Con	le <i>≠</i> #		1 3:30 o'clock
(County)				P	and recorded in
1. Public Land Survey	T 47N R 44	W <u>M-4</u>		Liber 6	of Corners
	TA			9 page 384	A DESCRIPTION OF THE PERSON OF
	T 47N R 43			Ramona Co	Lilian Nasa
2. Property Controlling	S_I_B_				egister of Davids
in Section	S T R				-Small of head
3. Miscellaneous	S T R		Re	gister of Deeds Si	amp & File Number
Property in Sec.	S T R				
4 Lot No .	Recorded Plat			- A B C D E	: FGHIJKLN
				أأأأ	
_				2 6 6 5	- - - - -
Quater Corner 1	.2 & 7; T.47 N.,	R.43-44 W.			
i Diahard I Drah	n in a field survey on <u>Apr</u>	i: 17.	19 08	5	-9-10-11-12-1
do hereby certify that under re-	quirements of P.A. 74, Michigan	P.A. of 1970, the corner	points mentioned	6 18 17	_16151413
in lines 1 and 2 above were i	n conformance with regulation uctions of the United States De	s and rules therefore : enartment of the Interio	as required in the or Bureau of Land	7	
Management or by a decree of	a Court of Law and/or that the c	orner points mentioned	l in lines 3, 4 and 5	8 19 20	_21222324
above were in conformance wi	ith the rules of the Michigan Bo- re-established, monumented,	ard of Land Surveyors of re-manumented - reco	or by a Decree of a	9	+++++
expressed below:	re-established, mondificated,	To monamento, 100	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	103029	-26 -25 -
NOTE: Not more than 4 of	corners, all in the same tow	n and range, may b	e recorded	11	- - - - - -
on this certificate	•			12 31 32	33 34 35 36
A Description of original	monument and accessories	and/or subsequent	restoration:	13	
	hed by Austin Bu			nal B.T.s -	Hemlock
16" S.67 W. 13	links (8.58')	- Sugar 7" S	.81 E. 37 1	inks (24.42	')
	l by Richard L. D				
	and from an origoipe with a 3" st				
	edar				new b.i.s.
10" Ye	ellow Birch	S.55 E.	25.1'		
	11ow Birch	s.57 W.	55.7		
	eel sign post	N.87 W.	2.1'	n 1/27/76	
B. Description of corner e	l in Gogebic Coun widence found and/or meth	od applied in restori	ng or reestablishing	corner:	
Corner research	on file with Go	gebic County	records.		
Recovered the m	onument as descr	ibed and the	bearing tr	ees as foll	OWS:
	dar	N.12 E.		ew nail)	0,,0.
	llow Birch	S.56 E.	23.13	11	
	ad Yellow Birch		<u>J4.47</u>	11 11	
7' St	eel sign rail	N.88 W.	2.10'		
The original B.	T.s are now both	badly decay	ed stumps.	The blazed	Y. Birch
	ered in 1975 is	now a Yellow	Birch stum	p, decayed	to ground
line.					•
3. Description of monume	ent for corner and accessor	es established to pe	erpetuate locating th	ne position of the o	corner;
New bearing tre	es referenced:			_ .	
5" Su	gar Maple	s.66 W.	42.44	111	of michie
10" Su	gar Maple	N.57 W.	29.16'	4 ")	RICHARD . DRAHN

igned by Richard L. Drahm

Date ____April 18, 1998

urveyor's Michigan License No. 21564

LAND SURVEYOR No. 21564

COUNTY BATABAN 445123