SURVEY-8---REMONUMENTATION

SEP 0 8 1998

9L ,				Register's Office		
	LAND CORNER RECORDATION CERTIFICATE					
SECTION For corners in	Filing Requirement of Act 74, Mich. P.A.			Received for record the		
		1	ł	14 724 day of MAY		
Gogebic (County)	Located In:	Corner Code ##		A. D. 1998 at 3:30 o'clock		
1. Public Land Survey	T <u>47N</u> R <u>44</u> W T R	M-7		Liber 6 of Corver	سوج	
	TR T47N_R 43_W	A-7		Page 387 Remone Collins, Dec:		
2. Property Controlling	SR STR			Register of Deade		
in Section						
Miscellaneous Property in Sec.	S T R S T R		Reg	rister of Deeds Stamp & File Number	er 	
4. Lot No, R	ecorded Plat			A B C D E F G H I J #	K L	
5. Private Claims				2	ŢŢ	
Coation Corner	13, 24, 18 & 19; T	. 47 N D 43-44	TeT.	3	\Box	
Section Corner	13, 24, 10 & 19; 1		14 •	4 7 8 9 10 11-	1.	
Richard L. Drahr	in a field survey on <u>Apri</u>	1 20, 19 98	:	5	++	
	uirements of P.A. 74, Michigan P.A conformance with regulations a			6 18 17 18 15 14-	 :	
current manual of survey instru	ctions of the United States Depa	rtment of the Interior, Bureau o	f Land	7	+	
·	Court of Law and/or that the corn to the rules of the Michigan Board			8 - 19 - 20 - 2122 - 23 -		
	e-established, monumented, re-	- ,		9	1 1	
expressed below:				10 30 29 28 27 26	- -2!	
	orners, all in the same town a	ind range, may be recorded	1	11	+ +	
on this certificate.				12 31 32 33 34 35	36	
A. Description of original n	nonument and accessories ar	nd/or subsequent restoratio	n:	131		
S.46 W. 15 links 10" S.26 E. 6 li Corner restored the first two B with a 3" stamps 6" Yell 6" Yell 10" Ceda	s (9.90') B. A inks (3.96')B. by Donald D. Lapp T.s (the second of ed brass cap and the low Birch N.6	Ash 10" N.28 E. 2 Ash 12" N.35 E. Dala (12585) on 6 One still scribed The following new 16 E. 16.2' 15 E. 7.7' 16 O W. 26.9'	9 11nk 32 1i /17/71 1). He beari	from the remains of set a $2\frac{1}{2}$ " iron pipe ng trees:		
	in Gogebic County					
	on file with Goge		_	25 011 0, 10, 12.		
	_	-				
	onument as describ Low Birch N.O	ped and the beari 16.05'	_			
	-	88 E. 7.70'	11	n n		
11" Ceda		30 W. 27.04'	11	H.		
4 X 4 X 7'	Cedar post N.5	<u>66 W.</u> 1.97'				
				and a decayed Black of the last two B.T.	.s.	
C. Description of monumer	nt for corner and accessories	established to perpetuate t	ocating the	e position of the corner:		

RICHARD
L. DRAHN
LAND
SURVEYOR
NO.
21564

signed by Richard L. Dralm

New bearing objects referenced:

Yellow Birch

Steel sign rail

Date <u>April 22, 1998</u>

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

6"

23.35

2.41'

S.11 W.

S.10 W.