

SURVEY &
REMONUMENTATION

SEP 08 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic

(County)

Located In:

Corner Code #

1. Public Land Survey

T47N R 44W K-12

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Quarter corner common to sections 35 & 36, T47N, R44W

I, John P. GOSS, in a field survey on Aug. 6, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt, U.S. Deputy Surveyor, in 1848.

Original bearing trees: Elm 10" S 10° W 20 links

Spruce 12" N 80° E 13 links

On October 17, 1969, Donald D. Lappala, RLS, USFS, restored corner position at record bearing and distance from the stump holes of the two original bearing trees and recoverable natural features. He set a 2½" I.D. galv. iron pipe with 3" circular bronze tablet which reads: T.47 N., R.44 W.; 1/4; S-35, S-36; R.L.S. 12585; 1969. He established the following reference objects:
14" White Pine - N 80° W - 77.8' ; 24" White Pine - N 40° E - 174.0' (dead)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

5" Yellow Birch - S 84° E - 10.3' (out) ; 6' Metal Sign Rail - N 15° W - 5.50'

He recorded said corner in U.S. Forest Service Liber X-21 on May 27, 1970.

Found monument and reference objects.

I updated the monument and accessories as noted below to state and county specification.

Act 74 research on file.

FILE GROUP APPROVED
Richard L. Drach 8/19/98
COUNTY REGISTER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the Found monument I established the following existing and new reference objects:

27" White Pine	N 80° W	77.73 to nail in side of tree
6' Metal Sign Rail	N 15° W	5.24' to face of post
3" Balsam	S 80° E	19.15' to nail in side of tree
4"x4" Cedar sign post	S 75° E	1.96' to face of post



Signed by John P. Goss

Date August 6, 1998

Surveyor's Michigan License No. 23509

U.S.F.S. No. X-21