

Register's Office } ss.  
Gogebic County }

Received for record the

Corner Code ~~##~~

21<sup>st</sup> day of July

A. D. 1995 at 1:40 o'clock

P m, and recorded in

Libor 5 of CORNERS

Page 273

Ramona Collins, Deputy  
Register of Deeds

**Register of Deeds Stamp & File Number**

1. Public Land Survey	Sec. 13	T <u>47N</u>	R <u>46W</u>	<u>M - 6</u>
		T <u>47N</u>	R <u>45W</u>	<u>A - 6</u>
2. Property Controlling	S _____	T _____	R _____	_____
in Section	S _____	T _____	R _____	_____
3. Miscellaneous	S _____	T _____	R _____	_____
Property in Sec.	S _____	T _____	R _____	_____

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

1/4 cor. comm. to sec's. 13 and 18

I, John P. Goss, in a field survey on May 27, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by John Burt on Sept. 7, 1847. Set post.

Original bearing trees: Sugar 12" S 24° E 35 links  
Sugar 20" S 83° W 20 links

John P. Goss in 1983 using Plymouth Mining Company map of 1920 reestablished this corner and recorded it in Liber 2 on Page 312 of Land Corners for Gogebic County. Established the following witnesses and distances: T.Pole N 41° W-39.51'; 5" Maple- N 43° E- 51.87'; centerline top nut fireHyd-S 24° W-25.08'; (2) concrete Monument - North- 58.26' & 189.41' from corner.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

I found (3) of the witnesses objects from John P. Goss certification.

I updated the corner monument and accessories as noted below to state and county specification.

Act 74 reseach on file with the County Register of Deeds Office.

**PEER GROUP APPROVED**

Richard P. Meralin 7/10/95  
COUNTY REPRESENTATIVE

**COUNTY REPRESENTATIVE**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2½" brass cap with a 2" stem at 1" below asphalt road surface. Cap is Stamed T47N, R45-46W; S-13, S-18, 1995; P.S. 23509. I established the following bearing trees and reference objects.

T.Pole	N 41° W	39.51'
10" Maple	N 48° E	51.87'
E top nut Fire Hyd.	S 24° W	25.08'

Reference Monument consisting of 2½"x30"  
aluminum monumnet with a 3¼" aluminum cap  
Stamped to indicate the corner position.  
S 39° E- 39.79' with a 6' steel rail and  
sign 1.08'.



Signed by John P. Liso

Date May 28, 1995

Surveyor's Michigan License No. \_\_\_\_\_ P.S. 23509

Fed. No. L-25