

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office } ss.
Gogebic County }

For corners in

Gogebic
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 47N R 47W

D-E-5

T R

003

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Received for record the
16 day of SEP

A. D. 1994 at 3:50 o'clock

P m., and recorded in

Lib. 5 of CORNERS

on page 113

Ramona Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Meander corner common to Sections 8 & 17, T47N, R47W.

I, John R. Garske, in a field survey on June 23, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- Original survey by William Ives, D.S. in 1848. A 7" hemlock is the original corner. Original bearing trees: hemlock 14" - N41°E, 29 links.

- Corner is shown on survey map for James Laird property from the early 1970's, source unknown. Corner position is marked with a 1" iron pipe just south of a barbed wire fence. Accessories: 14" elm - N20°E, 15.9 feet; 16" W. pine - N28°W, 53.8 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched for corner by compass and tape west from section corner common to Sections 8, 9, 17 and 16, T47N, R47W to the bank of the Montreal River. Searched area and could only find the bearing trees as noted above. Found a blazed 18" W. pine and a 14" dead elm, being a 4' stub. Re-established the corner position south of old fence line using found bearing trees. I monumented the corner as noted below to state and county specifications.

Research record form on file with County Register of Deeds Office.

PEER GROUP

Approved

Richard L. Drahn

9/14/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3/4" x 24" rebar in concrete with a 3 1/4" aluminum cap stamped: M.C. S-8, S-17, T47N, R47W 1994, RLS 28410. I established the following bearing trees and reference objects: existing W. pine 18" - N34°W, 53.73 feet; R. maple 6" - N86°W, 12.47 feet; sugar 6" - N61°E, 15.88 feet; twin sugar 6" - S30°E, 25.79 feet; steel sign post - S23°W, 1.43 feet.

Corner is approximately 18 feet from edge of Montreal River.

Signed by John R. Garske
Surveyor's Michigan License No. 28410

Date

8/31/94



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983