

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }  
Gogebic County } ss.

For corners in

Gogebic  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 47N R 47W

G-H-9

T R

005

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Meander corner common to Sections 22 & 27, T47N, R47W.

I, John R. Garske, in a field survey on June 13, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- Original survey by William Ives, D.S., in 1848. Set wood post. Original bearing trees: B. oak 6" - S45°E, 25 links; Cedar 12" - N12°W, 32 links.
- Survey of Ray Pawlak property by J.R. Garske, RLS 28410 dated 5/16/86. Set a 3" concrete monument with a 1/2" rebar from ties furnished by City of Ironwood Engineering Department, Date unknown: Accessories: Elder - South, 31.28 feet; willow - West, 8.40 feet; clump of 4 willows on river, nail in 18" branch - N.W., 66.52 feet; Power Co. "H" frame (hub on centerline) - S.E., 253.5 feet 1986 established new witnesses: P. pole - N15°W, 116.15 feet; S.W. corner building (K of C Hall) N33°E, 121.49 feet; P. pole - S67°E, 164.87 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found concrete monument at the corner position as noted above and checked with remaining witnesses. I updated corner as noted below to bring it up to county and state specifications.

Research record form on file with County Register of Deeds Office.

PEER GROUP

Approved

Richard E. Drahn

8/14/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3 1/4" stamped aluminum cap in concrete atop the found concrete monument. The cap is stamped to read: M.C., S-22, S-27, T47N, R47W, 1994, RLS 28410. I established the following bearing trees and reference objects: existing P. pole - N15°W, 116.51 feet; SW corner of building - N33°E, 121.49 feet; clump of 6 willows 24" - S55°W, 16.82 feet; steel sign post - S52°W, 1.65 feet.

Signed by

John R. Garske

Date

8/31/94

Surveyor's Michigan License No.

28410

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983