Register's Office

		R RECORDATION CERTIF			, water						
_	Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the										
For corners in		•		16 day of 56.77							
Gogebic	Located In:	Corner Code ##		A. D. 1994 at 4:00 o'clock							
(County)											
1. Public Land Survey S-21	T 47N R 47W	G-8-9					acorue	KI IN			
1. Public Land Survey 5 22	T R	(006)	Läber	5_		_0(COR	NAL	-3		
	T R		on p	we	125		_				
	T R				Col		. Dex	out	ti		
2. Property Controlling S	T R					gister			J		
	TR					Ū					
	T R		Register	of Dec	eds Sta	amo &	File	Numl	ber		
	T R		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
4. Lot No, Reco	rded Plat		——— А	вС	D £	F G	н	ı j	ĸ	_ м	
5. Private Claims				T	ŢŢ		Ţ	Ţ		Ţ	
M.C. to Sections 21 and 22				i	- i		-3-	Γí.		iΠ	
			3		7						
Tahu D. Camalro	Tul	94	*	7	- 8	-9-	10 	11-		12-	
John R. Garske in a field survey on July , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned				++	++	+ +	+		十		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				18	-17	-16-	—1 ¹ 5—-	1'4- i	+	13 I	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land				╁╾┼		+++	+	╁╌┼╴		-	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				-19	-20-	-21-	<u>2</u> 2	23-	+	24	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				+-	+	┵	+	┼╌┼╴			
expressed below:				30-	_29 -	-28-	<u>27</u>	<u>2</u> 6-		25—	
NOTE: Not more than 4 corne	ers. all in the same town an	d range, may be recorded	11			\perp	-	$\bot \bot$	-		
on this certificate.			12	31	-32-	_33	34	35	-	-36—	
51. 11.10 55. 11.15			. 13	$\perp \perp$				$\perp \perp$		1_	
A. Description of original mon	ument and accessories and	/or subsequent restoration:									
Original survey	by William Ives, D.S., is	n 1848. Set wood post.	Original bea	ring	trees:	Hem	ilock				
14" - N37°E, 42	? links; Fir 6" - N17°W,	27 links.									
The corner noci	tion was found by Ewart	C Muller RIS 15048 i	in Novembe	r 197	7 hv i	ısing	city				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 1/2" rebar with Muller's cap at the corner position which checks with the witnesses in his certificate. I updated the corner as noted below to bring it up to county and state specifications.

plat ties. He set a 1/2" iron rod at the corner loction and recorded the corner in liber 1 of land corners P. 498. Accessories: Willow 30" - due south, 9.45 feet; twin willow 40" - S40°E, 18.76

Act 74 research on file with County Register of Deeds Office.

PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the found 1/2" rebar with a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position. I also established the following bearing trees and reference objects:

W. birch 3" - N24°W, 34.49 feet W. birch 3" - N42°E, 18.60 feet Willow 24" - S04°W, 9.06 feet Steel sign post - N72°W, 1.71 feet

Signed by

feet.

No. 28410

OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

JOHN R GARSKE LAND SURVEYOR

REVISED JAN., 1983