

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office
Gogebic County

For corners in

GOGEBIC

(County)

Located In:

Corner Code #

1. Public Land Survey

T48NR 44W

G-8

T R

T R

T R

SURVEY &
REMONUMENTATION

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

JAN 05 2001

SECTION

Received for record the
26TH day of MAY
A. D. 2000 at 11:20 o'clock
A. M., and recorded in
Liber 7 of CORNERS
page 344
Cheryl Rippe
Dep. Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Quarter corner, Sections 21 & 22, T48N, R44W

I, John P. Goss, in a field survey on May 22, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, on Sept. 7, 1848.

Original bearing trees: Cedar 10" S 50° W 9 links (5.94 ft.)
Cedar 8" N 58° E 17 links (11.22 ft.)

Richard L. Drahn, on May 12, 1977, restored corner position by single proportionate methods. He set a 2" I.D. iron pipe with a 3" Brass tablet, stamped to indicate the corner position. He established the following reference objects:

9" Cedar - N 85° W - 51.2 ft.; 5" Cedar - East - 38.2 ft.; 11" Yellow Birch S 14° W - 29.5 ft.; 7' metal sign post - N 14° E - 1.7 ft.

He recorded said corner on April 25, 1979, in Liber 1, page 136 of Land Corners

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
No original evidence found.

Found Richard L. Drahn monument and accessories.

Act 74 research on file.

FREE GROUP APPROVED
Richard L. Drahn 05/24/00
COURT REESTABLISHING

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From found monument stamped to read: T.48 N., R.44 W.; 1/4; S-21, S-22; 1977; R.L.S. 21564, from which I established the following existing and new reference objects:

12" Cedar N 85° W 51.19 ft.
7" Cedar East 38.22 ft.
13" Yellow Birch S 14° W 29.37 ft.
6" Cedar N 46° E 4.22 ft.
7' metal sign post N 16° E 1.68 ft. to face
(All measurement taken to nail in side of tree)



Signed by John P. Goss

Date May 22, 2000

Surveyor's Michigan License No. 23509

U.S.F.S. No. P-13