SEP 0 8 1998

SECT		
------	--	--

LAND CORNER RECORDATION CERTIFICATE Kegister's Office ss.

For corners in	Filing	g Requireme	nt of Act 74, Mich.	P.A. 1970	Gogebic Count Receiv	ed for record the
Gogebig	Located In:		Corner Code ≠	-		lay of JONR
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_ 49N -	45.14	7. 11		A. D. 19.22	at 1:30 o'clock
Public Land Survey	т <u>48N</u> р т ғ		A-11	-	m	, and recorded in of Courses
	I				_	01
O December Controlling	S T _48N F		M-11		Romen a	LOSLIAM, DID
2. Property Controlling in Section	STF	` <u> </u>			H-MARINIECE	Register of Doede
3. Miscellaneous	S T F			Re	gister of Deeds St	amp & File Number
Property in Sec.	S T F	·		l		
4. Lot No,				·	- ABCDE	FGHIJKL
5. Private Claims		·····			2 6 5	4 3 2
Section Corner	30, 31, 25 &	36; T.48	N., R.45-46	W.	3	11111
			·		4 - 7 - 8 - 1	-9-10-11-12
Richard L. Drah: do hereby certify that under re					5	+++++
in lines 1 and 2 above were i	n conformance with regi	ulations and rul	es therefore as required	f in the	6 18 17	-1 6
current manual of survey instr Management or by a decree of		•			8 19 20	21 22 23 24
above were in conformance will Court of Law; established,					9	
expressed below:	re-established, monune	intea, re-mona	mented, recovered, loc	unu as	10 30 29	-28 -27 - 26 25
NOTE: Not more than 4 of		e town and ra	nge, may be recorde	d	' \	
on this certificate	•				12 31 32	-33 - 34 - 35 - 36
A. Description of original	monument and access	sories and/or	subsequent restoration	on:	13	··· /
Corner establis	hed by John B	urt on 9,	/10/1847. or	igina1	B.T.sH	emlock
20" S.54 E. 42						
Corner restored original B.T.s						
pipe with a 3¾"	stamped alum:	inum cap	and the foll	owing:	new B.T.s:	41 WIN 4 X 1 W 1 W
		N.62 V				
-	ugar Maple ugar Maple	S.88 I S.35 V	E. 22.21' V. 27.21'			
6' St	teel sign rai:	L N.48 I	E. 2.1'			
Corner recorded B. Description of corner e	in Gogebic Co vidence found and/or	ounty in method applie	Liber 2. Paged in restoring or rees	e 711 datablishing	on 12/10/84 corner:	•
Corner research						
Recovered the mo	onument as des	cribed a	and the beari	na tre	es as follo	ws:
6" St	ıgar Maple	N.61 W	√. 25.87'			
	ıgar Maple	S.85 E				
,	ugar Maple beel sign raij	S.36 W L N.50 E				
	_					
A stump hole rem decayed to below	mains from the	origina etill re	al Hemlock B.	T. and	a Sugar Ma	ple stump
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	· ground rine	SCITT IF	emains from C	ue orrô	ginai Sugar	в.т.
C. Description of moлume	nt for corner and acce	ssories establ	ished to perpetuate lo	ocating the	e position of the co	orner;
New bearin	ng tree refere	enced			01.4	IICHIG .
5" Y€	ellow Birch	N.09 E	39.66'		* RICHAI	RD T
	A <b>B</b>	EER GROW	R. APPROVED	-	* LANG	

Date <u>June 16, 1998</u>

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983