Si	JAVEY &		Proposition and Proposition	· .	
101	JAVEY & TON JUMENTATION				
0(	OT 0 8 1996			Register's Office	
-	OMMISSION		R RECORDATION CERTIFICAT	•	
	corners in	Filing Require	ment of Act 74, Mich. P.A. 197	70 Received for record the	
	Gogebic	Located In:	Corner Code =##	A. D. 19 96, at 9:40 o'clock	
	(County)	l One l Oth		Am., and recorded in	
1.	Public Land Survey	т <u>48N</u> я <b>49</b> W. Т Я	1-3-4	Liber 5 of CORNERS	
		T R	003	Ramona Collins, Ospaty	
2.	Property Controlling	T R S T R		Register of Deeds	
	in Section	S			
	Miscellaneous Property in Sec.	S T R		legister of Deeds Stamp & File Number	
4	Lot No. B	ecorded Plat		A B C D E F G H I J K L M	
				A B C D E F G H I J K L M	
•	M.C. between s	ec's. 10 & 11		3	
	Tohn D. Coac	Mov	L3 , <sub>19</sub> <u>96</u> ,	4 7 4 8 4 9 4 10 11 12	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					
in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					
	rt of Law; established, r essed below:	e-established, monumented, re-m	onumented, recovered, found as	10 30 29 28 27 26 25	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				11 12 31 32 33 34 35 36	
,				13	
	Description of original monument and accessories and/or subsequent restoration: Originalcorner established by William Ives on August 14, 1848. Set post.				
	Original beari	ng trees: Hemlock	18" S 39° E 10 li	nks	
		Cedar	lO" s 52 <sup>0</sup> W 10 li	nks	
	John R. Garske on line and 116 feet north of 1/4 corner set a 2" galvanized iron pipe with brass cap. Garske recorded said corner in Liber 2 page 132				
	of Land Corner	s for Gogebic Count	ty. The following re N-9.17'; 8" W. Birch	ference objects were	
	COURTINGE.	W. DIIOM II / N.	, , , , , , , , , , , , , , , , , , , ,	2 2 2.71	
_		idense found and/or mathod o	pplied in restoring or reestablishi	ng corner.	
	!				
I found the 2" galvanized iron pipe with 2" brass cap as no Garske certification and it checked with the witnesses in certification. I updated the corner monument and accessoric				es in John R. Garske	
		and county specifi			
:	Act 74 reseach	on file.			
			,		
		PEER GROUP APPROVED			
			<u> Kuellar</u>	OUNTY BEPRESENTATIVE	
C.	Description of monume	nt for corner and accessories e	stablished to perpetuate locating	the position of the corner:	
			· ·	lowing bearing trees	
	and reference			The state of the s	
•	By W. Birch	N 72° W	0.17' (tree is dead)	TE W GO WAY	
·	7" W. Birch	S 800 E 8 N 480 W 23 S 100 W 18	3.10'	JOHN P. \*	
		S 10° W 18	3.721	LARD * SURVEYOR	
	l" W. Birch 6'rail & Sign			No. 23509	
				MALEO TANO SULLE	
	1. 10.6	Horas	Data Mary 1	4. 1996	
Sign	ed by John 9	23509	Date May		
Surv	eyor s Michigan Licens	Fed. NO. F-		PPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983	

362

Fed. NO. F-G- 17