

COMMERCICLE

| V 83.1314 | LAND CORNE | R RECORDATION CERTIFICA | ATE |
|--|--|---|---|
| · | Filing Require | ment of Act 74, Mich. P.A. 19 | 970 |
| For corners in Grand Traverse (County) | Located In: | Corner Code # | |
| 1. Public Land Survey | T <u>25N</u> R <u>10W</u> T R T R T R | L-5 | STATE OF MICHIGAN GRAND TRAVERSE COUNTY RECORDED 27 DEC 96 2431 P.M. |
| Property Controlling in Section Miscellaneous Property in Section | ST R ST R ST R | | KARON ANDERSON REGISTER OF TEEDS Register of Deeds Stamp & File Number |
| 4. Lot No 5. Private Claims | , Recorded Plat | | A B C D E F G H I J K L |
| do hereby certify that under in lines 1 and 2 above were manual of survey instruct Management or by a decret 5 above were in conformar | P11, in a field survey on Noverequirements of P.A. 74, Michigan P.A. in conformance with regulations and rulons of the United States Department of a Court of Law and/or that the concession with the rules of the Michigan Bostablished, re-established, monument | and the corner points mentioned also therefore as required in the current and of the Interior, Bureau of Landrer points mentioned in lines 3, 4 and ard of Professional Surveyors or by a | 1 6 18 17 16 15 14 13 13 13 15 18 19 20 21 22 23 24 1 |
| NOTE: Not more than 4 on this certificate | corners, all in the same town and e. | range, may be recorded | 11 31 32 33 34 35 36 |
| L-5) North 1/4 Cor 8" N44°W 11 1 1872 recorded but no monume the North sid Gov't Cor lo L.1, Pgs.51-5 type or any | ks", U.S. Resurvey by S.S. i in L.1, Pgs.51-52 of the centation or wits were stated of Section 12 in this cations. E.P. Waterman 52 of Co. Surveyors Record wits. "Fd railroad rail tchell dated June 29, 19 | emlock stake witnessed by 5. Scranton dated July 18 ne Co, Surveyors Records ted on survey. Note: (same area in April of 1 Co. Surveyor visited thi ds, Waterman indicated Co in centerline of East-W | Beech 6" S67°E 33 lks and a Beech 52. William Slawson survey of June indicate that the cor was visited F.P. Tuller, Co. Surveyor worked on 891 and Fd railroad irons at other as Cor in 1902, survey recorded in crexists but did not give monument est road", an unrecorded survey by and survey on file with Mitchell 6 |
| B. Description of corne | er evidence found and/or method | applied in restoring or reestablis | shing corner: |
| stake in the dated June 29 the original iron pipe wi | centerline of Sparling Ro ,1990, and is accepted as corner. Remonumented th | pad", as called out in Ce a careful and faithful ais position with a 2 1/ | I rail settingvertical and a Cedar rtified Survey by Rbert F. Mitchell re-establishment of the position of 2" x 30" flanged bottom galvanized UNTY REMONUMENTATION, 6" below the |
| | | | UNANIMOUSLY ACCEPTED BY THE GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 10-10-10-10-10-10-10-10-10-10-10-10-10-1 |
| C. Description of monu (-5) North 1/4 Co | ment for comer and accessories r of Sec 14, T25N-R10W; | established to perpetuate location | ROBERT F. MITCHELL, P.S., CHAIMMAN |
| n 2 1/2# 20 | • | | |
| N09°E - 18" W S01°W - 32" M S76°E - 32" M | hite Pine - 39.55' aple - 24.90' | | |

Surveyor's Michigan License No._ 28417