

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. 25 N. R. 11 W.	F-13; J-11; K-11
2. PROPERTY CONTROLLING IN SECTION 33	T. 25 N. R. 11 W.	15
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. W.	
4. LOT NO., RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 29, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~
C. (continued)

15
Set 1"x36" pipe & cedar post
w/location tag
28" Maple N59°W 137.15'
6" R. Pine N28°E 60.35'
4" S. Pine S42°E 41.85'
Center E-W Co. Rd. Due N 21.5'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- F-13 Restored corner on split of ROW fences to east & west and in line with fence to south.
- J-11 Restored corner 33' S. of fence remains W. and 33' W. of fence remains N. (mostly down). Fits 1/16 corner fence to N. ¼ mile to E. Position is reasonably close to straight line through N¼ corner & center of Sec. 26; see Liber 5, pages 221 and 308.
- K-11 Restored corner in center of old E-W grade in line with fence N. Fits survey of Sec. 25, Liber 5, pages 217-220, 1903.
- 15 Established corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-13	J-11	K-11
Set std. Wexford Co. mon. (buried)	Set DNR mon. (buried 1.0')	Set 1" x 36" pipe (buried 0.5')
10" Apple S29°W 91.35'	6" R. Pine N26°W 69.8'	12" Ironwood S30°W 44.9'
P. Pole N76°W 183.25'	8" Trpl. Maple N63°W 46.5'	9" Maple S32°E 49.2'
28" W. Pine N11°E 173.60'	6" Maple S73°W 74.4'	14" Maple N40°E 55.3'
Center E-W Co. Rd. Due N 2'	Set cedar post w/loc. tag S45°E 25'	Set cedar post w/loc. tag Due S 16.5'
Set cedar post w/loc. tag Due S 33'		

SIGNED BY

Carl F. Roser

DATE

7-3-74

SURVEYOR'S MICHIGAN REGISTRATION NO.

12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

MAYFIELD TWP.
GRAND TRAVERSE COUNTY