MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 25 N.R. 12 W

			_	Grand Traverse	COUNTY
DESCRIPTION OF CORNER	Section cor	ner common to se	ctions 20-2	21-28-29	
CORNER HONUMENT	Left 3/h" p	ipe in place			
DATE MONUMENT PLACED A	ND WITNESSED _	April 18, 196	6		
WITNESSES TO CORNER	•••		· · · · · · · · · · · · · · · · · · ·	······································	
N		10" H. Maple	N 38 W	91.2 '	
2b	7	10" Elm	N 33 E	53•7'	·
CIRCLE CORNER REGISTERS	AND				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this Section. Found 3/hm pipe, surrounded by rocks, about 8m below surface. Falls in line with road centerlines all directions.

SURVEYOR'S SEAL

REGISTERED SAND SURVEYOR #10068 DATE April 21, 196