

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. R. 12 W.	E-8; F-7; G-7
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER _____

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 14, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- E-8** Reestab. $\frac{1}{4}$ corner at double over $\frac{1}{8}$ cor. (fd. pipe) & sec. corner (fd. 1" pipe) to N which fits fence remains to E (fence all down, dug-out sev. post bottoms). Comp. S.P. position between sec. corners to N & S would be 3.3' N & 2.2' E. See C.P. Tuller's survey of NW $\frac{1}{4}$ of Sec. 21, 1909, Liber 2, page 338 of old Co. Surv. Rec. at Register of Deeds.
- F-7** Fd. large stone for N $\frac{1}{4}$ corner Sec. 21 per C. P. Tuller survey of 1909 (Tuller fd. both govt. wit. stps. & old stake in ground). See Liber 2, page 338 of old Co. Surv. Rec. at Register of Deeds.
- G-7** Fd. 1 $\frac{1}{4}$ " iron in road intersection. For reference to old Co. Surv. see corner record G-6, W $\frac{1}{4}$ corner Sec. 15.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8	F-7	G-7
Set DNR Mon. & Cedar post.	Fd. large stone w/X on top;	Fd. 1 $\frac{1}{4}$ " solid iron rod in
7" Oak S61°W 51.17	replaced w/DNR Mon. (buried	¢ b-top rd. inters. N-E-S.
8" Twn. Maple N36°E 18.62	in road).	SW cor. old schoolhouse w/new
6" Maple S15°E 22.80	6" R. Pine N35°W 37.95	poured conc. found. N58°E 86.90
9" Twn. Oak S50°E 3.46	7" R. Pine N32°E 56.16	P. Pole S21°W 112.14
Ctr. N-S Trail Rd.	Set ced. post w/loc. tag	P. Pole N14°W 124.08
Due W 13'±	Due S 33'	¢ gravel rd. W Due S 2'±
	Fd. 2" pipe (Tuller's)	
	S00°25'E 33.15	
	Ctr. E-W dirt road Due S 8'±	

SIGNED BY Carl F. Roser DATE 4-8-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY [Signature] DATE _____

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



GRAND TRAVERSE COUNTY
GRANT TOWNSHIP

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET