

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. R. 9 W.	H-12
2. PROPERTY CONTROLLING IN SECTION 34	T. 26 N. R. 9 W.	8; 15
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 10, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- # 12 Set cedar post by found concrete monument by RLS Walt Fraser. Monument fits subdivision of Sec. 34 per controlling corners by previous department survey.
- 8 Set 1"x36" pipe and cedar post equidistant and on line between DNR monument for $\frac{1}{4}$ corner to west and found concrete monument by RLS Walt Fraser at center of section.
- 15 Set cedar post by 1"x36" pipe; as established in previous department survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-12			8			15		
Fd. 4" Conc.Mon. & Cedar Post			Set 1"x36" pipe & Cedar Post			1"x36" Pipe & Cedar Post		
6" Cedar	S30°E	8.0	10" Cedar	N13°E	14.4	16" Tamarack	N69°W	30.4
6" Cedar	S80°W	30.0	6" Cedar	N64°E	6.3	10" Cedar	N71°E	21.6
6" Cedar	N62°W	34.0	6" Cedar	S14°W	45.3	9" Cedar	S27°E	13.7
6" Cedar	N03°W	28.8						

SIGNED BY Carl F. Roser 4-28-77 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

UNION TOWNSHIP
GRAND TRAVERSE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET