

MAR 16 1994

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**
GRAND TRAVERSE
(County)

Located In: Corner Code #

1. Public Land Survey T 26N R 11W C-8
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
GRAND TRAVERSE COUNTY
RECORDED
30 DEC 93 10:17 A.M.
KARON ANDERSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, **Gary G. Wilson**, in a field survey on **December 17**, 19 **93**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-8: Original G.L.O. notes and witnesses.

Act 74's recorded by P. Stout in Sept. 1981 (Liber 2, Pg. 469) and by 2, Pg. 607) and both report a 3/4" iron pipe.

Robt. Mitchell in Sept. 1984 (Liber

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-8: No physical evidence of the original GLO witnesses were found.
Found 3/4" iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8: 1/4 corner common to Sections 19 & 20

Perpetuated with 2-1/2" X 30" flanged bottom galvanized iron pipe with TRAVERSE COUNTY REMONUMENTATION.

S45°W 1.20' 8" White Birch
N50°E 15.50' 6" Cedar
N18°W 7.83' 4" Cedar
S38°W 9.48' 8" Cedar

3-1/2" brass cap stamped GRAND

Corner approved by the Grand Traverse County Peer Review Group on 11-03-93.

Signed by Gary G. Wilson
Surveyor's Michigan License No. 25881

Date December 28, 1993

