LAND CORNER RECORDATION CERTIFICATE

For Corners In: Grand Traverse	Filing Re Located In	quirement of Act 74, Corner Code #	Mich. PA 1970	STATE OF NICHIGAN GRAND TRAVERSE COUNTY RECORDED
(County)	Locatod si	Oomer Gode #		30 DEC 99 3:45 P.M.
1. Public Land Survey	T <u>27N</u> R <u>9V</u> T R	V B-3		KARON ANDERSON
2. Property Controlling in Section S S	T R	SURVEY &		REGISTER OF DEEDS
3. Miscellaneous Property in Section S S	T R	ONUMENTAT IC MAR <u>22 2000</u>		of Dondo Charry & File Name
	corded Plat:		Keyister	of Deeds Stamp & File Number
5. Private Claims:		SECTION	A B C D	E F G H 1 J K L M
I, <u>Craig W. McVean</u> , in a field surequirements of PA 74, Michigan and 2 above were in conformance the current manual of survey in Interior, Bureau of Land Manager corner points mentioned in lines of the Michigan Board of Land established, re-established, monuted by the correct on this certification.	PA of 1970, the corner poe with regulations and rules structions of the United S nent or by a decree of a Corner, and 5 above were in coll Surveyors or by a Decremented, recovered, found a ners, all in the same to	ints mentioned in lines 1 therefore as required in lates Department of the lates Department of the lates Department of the lates of Law and/or that the informance with the rules ee of a Court of Law; is expressed below:	3 4 7 8 5 6 18 17 7 7 8 19 20 9 10 30 29 11 12 31 32	-9 10 11 12 13 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 16 15 16
A. Description of original mone	ument and accessories a	nd/or subsequent resto	. ration	
 Co. Surveyor Bk. – L.1 Fnd. old stake & large Co. Surveyor Bk. L.1, p buggy axle iron L.10, pg.132 -1915 – E correctly set from U.S. MDOT wit. card- 1964- 	ech, N55°W 28L to 16" Br , P. 406 –George Steele gov't Beech at N55°W 28 og. 515 – E.P Waterman .P. Waterman - buggy Ar Wit. years ago.	eech with 1 - 1894 30" O 3 L. 7" O -1907 - 6" M Kel iron -LCRC by pipe. 5" I	"x20" Iron Rod ak S85°W 46.70' ak N73°W 41.81' aple N41°W 65.37' ed Pine N68°E 52.33, S	toser -1977- fnd. 1 1/4" pipe raise Set Cedar Post w/loc. tag due W 3 leLaMater-1979 1 1/2 " Pipe
B. Description of comer evider				
B-3 - ¼ cor common to Sec. Waterman's & Steele S original corner.	6 & 7 – FND. 1" x 20" iro urveys. Buggy axel per '	n rod in 1 ½" I.D. x 3.2' Waterman accepted as	long iron buggy axel ca a careful and faithful pe	sing pipe in N-S Gravel Rd. Fits repetuation of the position of the
			,	
C. Description of monument fo	r comer and accessories	established to perpetu	ate locating the position	of the corner:
B-3 - Replaced iron rod in ax in ring of stone - down	le with 3 ¼ " ' Grand Tra 0.6' pped ½" iron #13026 – a		,	alvanized Iron pipe
N 42° W 50.01' to se N 75° W 41.74' to se S 81° W 46.68' to se N 66° E 52.18' to se	et N & T in NE. side 9 et N & T in NE. side 12 et N & T in N. side 30 et N & T in N. side 30 et N & T in NW. side 11 et N & S in NE. side 8	"S. Maple (CFF 'R. Oak Clp-4 (WRD, ('R. Oak (WR 'R. Pine (CFR)	R. WRD?)	CRAIG W.
Signed by:	y W. Ma	Dem Date	: <u>[</u> 2]13/19	PROFESSIONAL SURVEYOR No. 39088
REVIEW GROUP AS THE OFF CORNER UNDER MICHIGAN F ACT 345 OF 1990	*ICIAL			FESSION
HELD ON 1990 AT A MEE		FORM APPROVED BY MIC	HIGAN STATE BOARD OF P	ROFESSIONAL SURVEYORS JAN. 28, 19 Revised May 14, 19 Revised Jan. 19 Revised Oct. 19