For corners in		ER RECORDATION CERTIF rement of Act 74, Mich. P.A.		STATE OF MICHIGAN GRAND TRAVERSE COUNTY RECORDED
Grand Traverse	Located In:	Corner Code #		30 DEC 99 4:06 P.M.
(County)	Loodlod III.	Curier Code #		
1. Public Land Survey	T <u>27N_R</u> TR	9W <u>M-7</u>		KARON ANDERSON REGISTER OF DEEDS
2. Property Controlling	S TR_	SURVEY &	·	
in Section 3. Miscellaneous	S TR_ S T R	REMONUMENTATION	N.	
Property in Sec.	SR_	MAR 22 2000		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat			
5. Private Claims		SECTION	1 2	B C D E F G H I J K L H
I, <u>Craig W, McVean</u> , in a that under requirements of P.A. 7 mentioned in lines 1 and 2 above therefore as required in the curred Department of the Interior, Burea Law and /or that the corner points conformance with the rules of the of a Court of Law; established, reexpressed below: NOTE: Not more than 2 cothis certificate.	74, Michigan P.A. of 1970, the were in conformance with rent manual of survey instruction of Land Management or by a mentioned in lines 3, 4 and 6 Michigan Board of Land Suestablished, monumented, a	e corner points egulations and rules ons of the United States y a decree of a Court of 5 above were in rveyors or by a Decree	1	7 8 9 10 11 12 18 17 16 15 14 13 -19 -20 21 22 23 -24 -
A. Description of original mo	nument and accessories	s and/or subsequent restoration:		
White Pine 20" N50°\ - GLO, T27N, R8W – I White Pine 28" N89° -1934, M. Schaaf +/- i -1967, K.J.Ostling-ME with axe marks falls i 6" Red Pine S41°W 6 -1967, Consumers Po 10" Pine N46.5°E 27 -1973, LCRC L.1, pg.: N45°E 27.32' 10" Jac 3. Description of corner evide M-7 - Standard corner comn Found 4" DNR Alumin well preserved with ha exactly so Schaaf pro	E 20 links, Yellow Pine index fnd. DNR Cor. Rec. – Fnd. pip n line with fire lanes all d 60.6', 18" Red Pine wer Co. P. Perla – Fnd. 0', 18" Pine S52 166 - Kal. Co. Rec. – J. Wock Pine, S52°E 30.64 ence found and/or method non to sec. 13 & 24, T27 tum cap in intersection of ack marks. Schaaf recovered.	18" S35°W 77 links 16" S21°E 42 links be in concrete mon. per M.Schaalirections. Good original corner. S52°E 30.3', 9" Jack Pine N. concrete mon. 5°E 30.5', 6" Pine S41°W 60.86 od applied in restoring or reestable N,R9W and Sec. 1& 19 T27N, R. firetanes, down 1'. Also found the corner position in the 30 ce of the corner monument. DNR	Set 1" pipe wild 145°E 26.9', 60.6' ground 5' 7"Red Pine blishing corner 8W- SW Yellow Pi	ne GLO BT stump,
C. Description of monument to	for corner and accessorie	es established to perpetuate loca	ating the positi	on of the corner:
alongside. Reset Sch brass cap on 2 ½" X 3 S52°E 30.87' to set n S42°W 60.89' to set n N36°E 29.87' to set n N52°W 30.38' to set r East 33' to set Blue C	aat mon. – down 3'+ at E	0" Red Pine (KJO, CPC, JW 'White Pine scribed "XBT' " Red Pine tag	th 3 ¼" 'Grand)	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088
O. in	n m AI		15/	POFESSIONAL
igned by Charles	v. INC Ven		Date _/ 2//2	17999
urveyor's Michigan License N	to. <u>39088</u>	UNANIMOUSLY GRAND TRAVE FOR HEVIEW GROUP CORNER UNDER ACT 345 OF 19	ACCEPTED B BEACOUNTY AS THE OFF MICHIGAN P 90, AT A MEE	Y THE ROSEPPROFESSIONAL SURVEYORS, JAN. 28, 1971 ICIAL REVISED MAY 14, 1976 UBLIC REVISED JAN., 1983 ING REVISED OCT., 1995

ROBERT F. MITCHELL, P.S., CITAIIIMAN