## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

4. Lot No: Recorded Plat:				•		
T R  2. Property Controlling in Section  S 15 T 27N R 9W 6 S 15 T 27N R 9W 7  3. Miscellaneous Property in Section  S T R  S T R  Register of Deeds Stamp & File I  4. Lot No: Recorded Plat:  5. Private Claims:  1, Craig W. McVean, in a field survey on May 17, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	Grand Traverse	rand Traverse Located In Corner Code #				
5. Private Claims:  1. Craig W. McVean, in a field survey on May 17, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	<ol> <li>Public Land Survey</li> <li>Property Controlling in Section</li> <li>Miscellaneous</li> </ol>	S 15		R 9W R 9W R		Register of Deeds Stamp & File Nu
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	5. Private Claims:  1. Craig W. McVean, in a field survey on May 17, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may					1 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 12 15 14 13 17 16 15 14 13 17 18 19 10 10 10 10 10 10 10 10 10 10 10 10 10
	NOTE: Not more than 2 corners, all in the same town and range, may					10 30 29 28 27 26

- A. Description of original monument and accessories and/or subsequent restoration:
- 6 CSR- L.2, P. 290-E.P.Waterman 1907 Drove 2" +/- water pipe-it is correctly placed E & W but it is incorrect N & S-being to far S & should be corrected at some future survey. I did not do enough surveying to locate it correctly.
  - Unrec. Survey-Mitchell & Assoc. #930601- 1993-iron set
- 7 CSR- L. 2, P. 290-E.P. Waterman-1907-Fd. long set stake 2' W. of straight line between NE & E 1/4 corners.
  - -Unrec. Survey- Mitchell & Assoc. #930601-1993-Fd. 1/2" iron pipe
  - -Beryl Jones notes-1996- Fd. 1 1/4" iron pipe. N60°W 30.05' to 38" Maple

S60°W 32.35' to 12" B. Locust

S12°E 58.56' to 40" Maple N58°E 42.26' to 8" Maple

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- NE 1/16, Sec. 15, T27N, R9W Fnd. ½" x 18" CIR #28417-30079. Also Fd. 1 ½" well point N22°36' 4.51' of 1/2" CIR. Well pt. at fence remains E, W & N. Well pt. could be Waterman's temp. position but his numbers would seem to indicate his pipe would be 12'± S. of Mitchell's CIR. Accept 1/2" CIR as best available evidence of the position of the corner.
- 7 N 1/16 corner common to Sec. 14 & 15, T27N, R9W Previous monument obliterated during recent rd. const. Set 2" Alum. Cap on 5/8" x 34" Rebar per B. Jones witnesses. Fits Waterman's and Mitchell's distances N & S. Calculate position to be 1.34' W. (2'-EPW) of line between I-5 & I-6. 1' +/- W. of CL N-S gravel rd. 2" AC accepted as the best available evidence of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 6 Replaced 1/2" CIR# 28417/30079 with 2" Alum. Cap on 5/8" x 34" Rebar. Added ring of stone. N45°E 19.51' to set N&T in NW side 8" W. Pine \*S37°W 35.69' to set N&T in NW side 7" R. Oak \*S45°E 33.27' to set N&T in NE side 12" R. Pine

S13°E 46.84' to set N&T in W. side 14" R. Pine N23°W 4.51' to fd. 1 1/2" I.D. Iron Well Pt.

Set Blue Carsonite post w/ loc. tag 1' SE

\* B. Jones' N&T alongside

Surveyor's Michigan Licerse No.:

7 - 2" AC on 5/8" x 34" Rebar

West 33.00' to Set 2" AC on 5/8" x 34" Rebar on line with Blue Carsonite Post w/ loc. tag.

N62°W 30.06' to set N&T in N side 34" S. Maple (BJ) S62°W 32.30' to set N&T in SE side 12" B. Locust (BJ)

S22°E 58.53' to set N&T in SW side 38" S. Maple (BJ) N56°E 42.40' to set N&T in NW side 16" S. Maple (BJ)

Set N&T @ Previously Set N&T by Beryl Jones

Date:

22/2001

OF MICHIGAN CRAIG W McVEAN PROFESSIONAL SURVEYOR No. 39088

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL

Revised Oct. 1995