SURVEY & REMONUMENTATION

APR 27 1995

003 PAGE 583

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in Grand Traverse		Filing Requirement of Act 74, Mich. P.A. 1970						OF 1						
		Located In:	Corner Code ≄≠			GRA		RAVE: RECO!			A. A.	٠ ٠		
1.	Public Land Survey	7 27N R 12W			3() DEC	94	1:35	5 P.A	. ~	i sanaran I	,		
		T R T R T R		KARON ANDERSON REGISTER OF DEEDS										
	Property Controlling in Section	S T R												
3.	Miscellaneous Property in Sec.	S T R S T R		Reg	gister (of De	eds	Stan	ъ & ——	File	Nun —–	nbe	r 	
		ecorded Plat			· A	в (C D	E I	F G	н	ı j	ĸ	L	м
5.	Private Claims			·····	2	e I			Ŧ	-3-				7
,	South D. Chave	70-	mamban 21	0.4	4	 	- - 8-	1 9	<u></u>	- -			— — (:	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned							-{-	+-			╁╌┤	\dashv		\dashv
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land								-	-	-15 	<u> </u>	4	1: 1	3
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a								- 2 2	ı -	-22 	 2	3	2 1	4
	Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							-2	-	 	-2	6—	- -2	5
NC	OTE: Not more than 4 co on this certificate.	ners, all in the same town and range, may be recorded			11	31-		3		-34-	-3	5	3	6
A.	Description of original r	monument and accessories ar	nd/or subsequent restorati	on:	13 📙		h							

K-10: 1/4 Corner common to Sections 26 & 25, T.27N., R.12W.: U.S.Survey: Post witnessed by Beech 10", S82°W, 29 links; Black Oak 24", S45°E, 24 links; H.F. Northrup, in 1898, found stake in Highway nearly on East-West fence; C.P. Tuller, in 1905, found cedar stake surrounded by stones per Bk. 1, Page 167; LCR by Mitchell dated June 3, 1993 per Liber 03, Page 410.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod with P.S. cap in monument box over 3/4" iron pipe found 36" deep, in centerline of Bass Lake Road on fence line. corner is accepted as a careful and faithful perpetuation of the position of the original corner.

UNANIMOUSLY ACCEPTED BY THE GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING CHELD ON 12-15-24 NJUO

ROBERT F. MITCHELL, P.S., CHAIHMAN

TE OF MICHIGA

GARTH

D. STOW LAND SURVEYOR

> NO. 25875

Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-10: 1/4 Corner common to Sections 26 & 25, T.27N., R.12W. Set 2-1/2" x
30" flanged bottom galvanized iron pipe with 3-1/4" brass cap stamped
GRAND TRAVERSE COUNTY REMONUMENTATION in centerline of Bass Lake Road
S46°W 100.32' 16" White Pine
N79°W 32.70' Power Pole

N60°E 53.19' 8" Red Pine

S58°E 64.94' 8" Red Pine

Corner approved by the Grand Traverse County Peer Review Group ξ

on 12-15-94. Signed by _ Cartif 25875 Surveyor's Michigan License No. .

_ Date _

250 LAND SURVEY