SURVEY & SURVEY & REMONUMENTATION

Marin Labor.

JUN 0 1 1998

Si	-,	 7"		N
9	-(1	!_	W

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	- ,	,	
-	Grand Traverse		1	
`	(County)	Located In:	Corner Code ++	
	1000,	18		
	Dublic Land Comme	· -	(K-1.3)	\
1.	Public Land Survey	т <u>27/N</u> R <u>9W</u>	(^-1-3 /	
		T R		
		T R		
		T R		
_				
2.	Property Controlling	S T R		
	in Section	S T R		
3	Miscellaneous		i i	m • • • • • • • • • • • • • • • • • • •
٠.				Register of Deeds Stamp & File Number
	Property in Sec.	S R		
				N.
4.	Lot No.	. Recorded Plat		•
				A B C D E F G H I J K L
Ů.	i iivate Olaiiiis	· · · · · · · · · · · · · · · · · · ·		
				3
, ,	Robert F. Mitchell	_ , in a field survey on	October 40 03	
اراڪ مام	hard to the the	_ , in a new survey on	<u> 00.00161</u> , 19 <u>90</u>	5
ao.	nereby certify that under i	requirements of P.A. 74, Michigan P.A	A. of 1970, the corner points mentioned	6 18 17 16 15 14 14
			nd rules therefore as required in the	
			rtment of the Interior, Bureau of Land	7
Мa	nagement or by a decree o	of a Court of Law and/or that the corr	er points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
abo	ove were in conformance	with the rules of the Michigan Board	of Land Surveyors or by a Decree of a	13 20 21 22 23
			-monumented, recovered, found as	9
	pressed below:	, to bottomorrou, monomorrou, to	monamontos, recercios, round as	10 30 29 28 27 26 25
•				20 27 20 25
NO	OTE: Not more than 4	corners, all in the same town a	and range, may be recorded	11
	on this certificat	e.		12 31 32 32 34 35 36
				13
A.	Description of origina	al monument and accessories ar	nd/or subsequent restoration;	
	K-1; Section Co	orner common to Sections 3	5 and 36, T28N-R9W and Section	ons I and 2, T27N-R9W; "Wood post
	witnessed by Hemi	lock 18" N65°W 18L and Hemlo	ck 18" S60°E St. " CTO survey b	y Lucius Lyon, dated May 1850. An
		or IT Classical and A 1 and	on to book a say one barvey b	y micros byon, dates hay 1000. Mi
	uncerted survey b	y w. Slawson recorded in	liber 1, Page 26 of the G.T	. Co. Surveyors Records states no
	monument type or	witnesses for this corn	er. A survey recorded in Lil	ber 1, Page 368 by E.P. Waterman,
	County Currowan	dated August 10 1000 and1	- for the old state and come	Total 1, rage 500 by Est Matteriali,
	country ourveyor,	Garen Wigner 10, 1909 Call	s for Am ord stake and stone	along set and witnessed by an Ash
	tree 6" N15 3/4	W 80.7' and also a fence	corner post N43 3/4°E 47.5'."	A survey the Michigan Dept. of
	Transportation an	nd dated 1964 calls for a	"found 1" from her and stone	es witnessed by a 12" Cedar N62°E
	65 791 and a 11"	Film C7901/ 45 721 and normal	-1-002017 20 7/1 11 177	S withersen by a 12 Cental NOZ E
	021/0 am a m	Em 2/0 M 42./2 and power	hore 202 M 20.40. WIT CELLI	fied surverys recorded in the G.T.
	Co. Court House u	nder Public Act 132, have ca	lled for a l" square iron on t	heir certificates.
			<u>-</u>	
ь	Description of corner	ovidence found and/or mathod	applied in rectoring or reactablish	ing corner:
В.	Description of comer	evidence lound and/or method	applied in restoring or reestablish	ing conter.
	K-1: Section Co.	mer common to Sections 35	and 36 T28N-RGU and Sections	s 1 and 2, T27N-R9W; Found a 1" x
	K 19 DECLIOI OO	thet compt to pections 33	and 50, 120N-RSW and Sections	; 1 am 2, 12/N-RSW; Found a 1 X
	40" square iron	bar set over several medium	stones and is accepted as a ca	reful and faithful perpetuation of
	the position of	the original corner. Remons	monted position with a 2½" v	30" flanged bottom galvanized iron
	-44 310 3	The original coeffice. Renorm	ECT COLUMN DESCRIPTION OF ALL	50 Tranger fortun garvantzed from
	pipe with 3% or	ass cap stamped GKAND IKAVI	RSE COUNTY REMONUMENTATION 9"	below the surface of a 20' wide
	East and West gra	wel road, left existing iron	and stones in bottom of hole.	•
	•			
		•		
				•
			•	
^	Description of manus	nont for corner and accessories	established to perpetuate locating	a the position of the corner
U.				
	K-1; Section Cor	ner common to Sections 35 ar	d 36, T28N-R9W and Sections 1	and 2, T27N-R9W;
				•
	2k" v 30" flan	ged bottom galuanized in	n pine with 3k" broce cor	stamped GRAND TRAVERSE COUNTY
	KEPIONUMENTATION 9	Detow the surface of a 20.	wide East and West gravel roa	ıg÷
	M3E9E OH 0-3	75 50 l		
	N35°E - 8" Cedar			
	N62°E - 14" Cedar	- 66.251	<u>.</u>	
	S76°E - 8" Cedar		Corner Approved b	y the Grand Traverse County
			Peer Review Group	on 11/3/93.
	SO3°W - guy pole		•	on 11/3/93.
	North - centerlin	e of East-West gravel road 2		on 11/3/93.
			. 0	5 "/ \ T
		()-0:0:	$\langle 0 1 \rangle$	ROBERT F. V & T
	() (ソング ナ レングイ	\	## MITCHELL *\
	<i>L</i> '/\ 7	WIXI	ルリ レ	PROFESSIONAL
e:-	and by	$X \cup X \cup$	DateDec	cember 28, 1935 SURVEYOR 6
ΟlÇ	gned by			No.
٠.	rveyor's Michigan Lice	nse No. 28417		
ou	nveyor s ivincingan Lice	1100 NO	FDRM	APPROVED BY MICHIGAN STATE TO BE THE SULVEYOR . 15
	,	•		OFFICE ON THE SECTION . 15
				O () The THE TURN ON THE SECOND !