LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

| Surveyor's Name: <u>Stephan J. Szyszkoski</u> | | ki Field | Survey Date: | April 24, 2017 | | | | |
|--|-----------------------------------|------------------------------------|-----------------|----------------|---------------|-----------|--------|--------------|
| For corner(s) in: Houghton | | | y AB | CDF | F G H | | - 1 NA | |
| Original Public Land Survey Corner a. S T 51N R 35W S T R | | Corner Code K4 (GCDB 600540) | 2 6 3 4 7 | 5 | 9 - 10 | J K | | 2 |
| S S Property Corner | TR | 1/16 Corner Code | 5 618 | 171 | 6 15 | -14 | | 4 5 6 |
| b. S 12 b. S 11 S | T 51N R 35W T 51N R 35W T R | 3 (GCDB 600560) 7 (GCDB 600560) | 7 8 19 9 | 20 -2 | 1 22 | 23 | | 7 8: 9 |
| s | TR | | —10 —30 11 | 29 2 | 8 27 | 26 | 25 | 10 11 |
| Part A. Corner History | | | 12 31 13 A B | | 3 34 F G H | 35 J K | - 1 | 12 13 |

a.) Quarter corner common to Sections 11 and 12. 1969 - A.O.Enger RLS reestablished the position for the corner following a careful examination of the position of a 1966 reestablishment by Billy D. Buckler, RLS. The 1971 recording of the Enger reestablishment accounts for the reestablishment in detail. Mr. Enger set a 1"IDx36" iron pipe with 4" aluminum cap. W.Spruce 12" S65°W 82.5 links, W.Pine 6" N36°E 48 links.

b.) North 1/16 corner between Sections 11 and 12. Not previously monumented.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1969 monument of record, in good condition, and at record bearing and distance from the 1969 W.Pine NBT, found in good condition with overgrown blazes. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

b.) Established the position for the corner midway and on the Section line between Section corner 1306.55' north and Quarter corner 1306.55' south.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
W.Pine N41°E 31.65' old blazes (forgot to note DBH)
5" Cherry S87°E 46.3' mrkd "1/4S NBT"
12" Cherry S61°W 3.3' do
4" Cherry N21°E 36.1' do
Set sq'd cedar post adjacent.
E= 7870310.90 N= 228888.93

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Balsam S36°E 4.45' mrkd "1/16S NBT"
10" Maple S09°W 16.1' do
6" Sugar S60°W 20.35' do
6" Sugar in clump N55°W 9.3' do
Set sq'd cedar post adjacent.
E= 7870320.11 N= 229287.01

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datuments. Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

07/20/2017

Professional Surveyor's License No.: 33986 page 1 of 1
Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

STEPHAN J SZYSZKOSKI PROFESSIONAL SURVEYOR No. 33986

OF MIC