## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## LAND CORNER RECORD

		Houghton	·COUNTY
,		T	R <b>35W</b>
DESCRIPTION OF CORNER	1/4 corner between Sections 1	1 and 12	
CORNER MONUMENT	1" I.D. x 36" iron pipe with	4" aluminum c	вр
DATE MONUMENT PLACED AND	WITNESSED July 28, 1969		
WITNESSES TO CORNER	W. Spruce 12 865°W 82 1k	s. "1/4S, NB	Ţ#
N	W. Pine 6 N36°E 48 lks.	"1/4S, NBT"	
di	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed on an old E & W fence line 1.45 chains East of an old fence corner. The undersigned believes that the fence corner itself is not the original location of the 1/4 post, because of lack of harmony with stream crossings along the section line and with other old fences north and south of this corner. This fence was found to be 119.94 chains south of an original corner on the north township boundary, or 0.85 chains shorter than the record distance of 120.79 chains.

The aforementioned E & W fence line is mentioned in Corner Record of B. D. Buckler, dated 6/3/1966, as being about 2 chains north (actually 1.80 chains) of his calculated corner position. This places his corner 121.74 chains South of the original corner on the north township boundary, or 0.95 chains longer than record. Measurements along section lines between Sec. 10 & 11 and 2 & 3, as established by proportionate measure from original corners, indicate a distance of 158.34 chains, or 1.36 chains shorter than the record of 159.70 chains; similarly, distances on section lines between Sec. 9 & 10 and 3 & 4 show 159.10 chains, or 1.56 chains shorter than the record 160.66 chains. This would indicate that N & S

SURVEYOR'S SEAL

action Char DATE 1/22/11
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing