

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 9 T 51N R 36W	F4
	S T R	(GCDB 340540)
	S 9 T 51N R 36W	9
3. Miscellaneous Property in Sec.	S T R	(GCDB 360540)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 09/16/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F4) Center of Section 9. Not previously monumented.

(9-Sec. 9) Center-East 1/16 corner, Section 9. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F4) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners.

(9-Sec. 9) Established the position for the corner midway and on a straight line between Center of
Section 9 1313.17' west and Quarter corner G4 1313.17' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Hemlock N45°E 9.35' mrkd "C1/4 BT"
10" Maple S21°E 2.2' do
11" Y.Birch S57°W 7.8' do
11" Maple N25°W 22.7' do
Set sq'd cedar post adjacent.
E= 7856546.296 N= 229189.531

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Tamarack N24°E 40.6' mrkd "1/16S BT"
3" Tamarack N59°E 16.7' do
8" W.Pine S31°W 33.2' do
4" W.Pine N73°W 13.05' do
Set sq'd cedar post adjacent.
E= 7856946.194 N= 229205.280

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski Date 03/12/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division