

Houghton Co.

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 52 N. R. 35 E. W.	J11
2. PROPERTY CONTROLLING IN SECTION 26	T. 52 N. R. 35 E. W.	5, 10, 11
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
Corner J11: Original Monument and Accessories Not Found. Found Iron Pipe set by Peter A. Larsen from original bearing trees in 1923.

Corner 5: Not Set on Original Survey Nor Subsequently Apparently.

Corner 10: Not Set on Original Survey Nor Subsequently Apparently.

Corner 11: Found 1 3/4" I.D. x unknown length iron pipe set by Peter A. Larson on subdivision of section prior to 1925.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner J11: Re-established on 5-11-78 at pipe.

Corner 5: Established on 5-17-78 midway and on line between corners north and south.

Corner 10: Established on 5-17-78 midway and on line between corners north and south.

Corner 11: Re-established on 5-11-78 at Iron Pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner J11: Set 1" I.D. x 36" Iron Pipe with 4" brass cap.

7" Sugar N37E 3.4 ft. 1/4S, NBT

5" Sugar N72W 14.6 ft. 1/4S, NBT

7" Yellow Birch S02W 13.8 ft. 1/4S, NBT

Corner 5: Set 1" I.D. x 36" Iron Pipe with 4" aluminum cap.

7" Sugar N48E 10.2 ft. 1/16S, BT

5" Sugar S57E 10.3 ft. 1/16S, BT

8" Sugar S24W 23.9 ft. 1/16S, BT

18" Sugar squared N49W 2.6 ft.

Corner 10: Set 1" I.D. x 36" Iron Pipe with 4" aluminum cap.

10" Yellow Birch S57E 5.1 ft. 1/16S, BT

6" Sugar S16W 13.7 ft. 1/16S, BT

12" Sugar N76W 31.8 ft. 1/16S, BT

Corner 11: 1 3/4" I.D. x Unknown length Iron Pipe

12" Sugar S03W 11.2 ft. 1/16S, BT

5" Sugar N53W 9.8 ft. 1/16S, BT

6" Maple N63E 11.2 ft. 1/16S, BT

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE July 17, 1978

Keith L. Sackett  
Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006