

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 16 T 52N R 36W S _____ T _____ R _____ S 18 T 52N R 36W	10 (GCDB 300420) 9 (GCDB 160440)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10/29/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 16) South 1/16 corner between Sections 16 and 17. Not previously monumented.

(9-Sec. 18) East 1/16 corner, Section 18. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 16) Established the position for the corner midway and on the Section line between Section  
corner 1332.98' south and Quarter corner 1332.98' north.

(9-Sec. 18) Established the position for the corner midway and on a straight line between Quarter  
corner 1337.58' east and the Center of Sec. 18 1337.58' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" Sugar N11°E 10.75' mrkd "1/16S BT"  
9" Y.Birch N89°E 13.2' do  
12" Maple S36°E 5.4' do  
9" Sugar N84°W 6.2' do  
Set sq'd cedar post adjacent.  
E= 7855969.413 N= 236727.550

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" Sugar N50°E 15.85' mrkd "1/16S BT"  
6" Sugar S65°E 20.6' do  
10" Sugar S04°W 23.0' do  
11" Sugar N59°W 12.55' do  
Set sq'd cedar post adjacent.  
E= 7853963.239 N= 237223.478

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL0502: N= 234995.272 m. E= 7857774.766 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

