

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County) Located In: Corner Code #
1. Public Land Survey T R
2. Property Controlling in Section S 33 T 52N R 36W 3 (GCDB 300160)
3. Miscellaneous Property in Sec. S T R 7 (GCDB 400160)
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 10/14/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 33) North 1/16 corner between Sections 32 and 33. Not previously monumented.

(7-Sec. 33) North 1/16 corner between Sections 33 and 34. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 33) Established the position for the corner midway and on the Section line between Section corner 1317.92' north and Quarter corner 1317.92' south.

(7-Sec. 33) Established the position for the corner midway and on the Section line between Section corner 1343.68' north and Quarter corner 1343.68' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar N26°E 26.85' mrkd "1/16S BT" 4" Balsam S65°E 13.8' do 12" Basswood S24°W 3.15' do 4" Ironwood N78°W 10.2' do Set sq'd cedar post adjacent. E= 7855902.858 N= 232766.889 The center of Pike Lane Rd. is approx 1.8 ch. east.

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Maple N35°W 5.9' mrkd "1/16S BT" 7" Maple N50°E 11.85' do 7" Hemlock S61°E 15.15' do 8" Hemlock S71°W 23.4' do Set sq'd cedar post adjacent. E= 7857542.834 N= 232689.680

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0502: N= 234995.272m. E= 7857774.766m.

Signed by [Signature] Date 10/20/2015 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division