

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: Oct. 4, 2016

For corner(s) in: Houghton County

## Original Public Land Survey Corner

## Corner Code

S          T          R           
S          T          R           
S          T          R           
S          T          R         

## Property Corner

## 1/16 Corner Code

a. S 29 T 52N R 36W 4 (GCDB 220260)  
a. S          T          R           
b. S 29 T 52N R 36W D10 (GCDB 240240)  
b. S          T          R         

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A. Corner History

a.) Northwest 1/16 corner, Section 29. A 1-1/2" ID iron pipe was found by the undersigned in 1998. Found no other record.

b.) Center of Section 29. A 1-1/2" ID iron pipe was found by the undersigned in 1998. Found no other record.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) At a position substantially at the intersection of straight lines connecting opposite 1/16 corners (those to the north, east, and west known to be monumented), I found a 1-1/2" ID iron pipe with a 1" sq. iron pin set inside of it. Found 4 witnesses trees with overgrown blazes facing the corner in which trees I found measuring nail with tags PS #32336. Accepted the pipe as a careful and faithful determination of the position of the corner.

b.) At a position that is substantially the intersection of straight lines connecting opposite 1/4 corners of Section 29, I found a 1-1/2" ID iron pipe, projecting 1.4' above ground, with overgrown blazes on 4 trees marked as witnesses facing it. The witness trees contain measuring nails with tag PS #32336. Accepted the pipe as a careful and faithful determination of the position of the corner.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Found 1-1/2" ID iron pipe with 1" sq. pin inside. Found measuring nail with tag #32336 in:  
14" triple Maple N52°E 12.8' overgrown blazes  
4" Ironwood S58°E 6.15' do  
6" Sugar S62°W 25.5' do  
8" Sugar N57°W 18.85' do  
Set sq'd cedar post adjacent.  
E= 7854727.957 N= 234383.858

(b.) Found 1-1/2" ID iron pipe. Found measuring nails with tags #32336 in:  
11" Sugar N56°E 22.65' overgrown blazes  
12" Sugar S65°E 6.4' do  
4" Sugar S52°W 15.45' do  
6" Sugar N38°W 15.85' do  
Set sq'd cedar post adjacent.  
E= 7855128.937 N= 233986.378

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters  
Coordinate Reference: NGS PID RL0502, E= 7857774.767 m. N= 234995.272 m.

Stephan J. Szyszkoski

11/03/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

