

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N R 36W

19

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

May 21 1998

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 22-23-26-27. Established in 1846 by Sylvester Higgins: 1) North btwn 26-27 ...80.00 2) Set post cor. Sec 22,23,26,27. 3) Hemlock 13 N30E 8, 4) do 12 S74W 25. North between 22-23 ...5) 20.00 Enter tam'k swamp E NW, 6) 25.00 leave tam'k swamp, 7) 27.30 Hemlock 12, 8) 33.50 Intersect small lake and set meander post, 9) W. Pine 30 S20E 31, 10) Y. Birch 10 S15W 30...11) 40.00 Set 1/4 Sec. post. East random btwn 23-26, 12) 7.00 Enter low wet lands NE&SW, 13) 12.38 Leave low wet lands...West corrected btwn 23-26 14) ...67.62 Cedar 12, 15) 79.99 Sec. corner. Corner recorded in 1984 by R.A. Mick, RLS 16936, Vol. 2, Pg. 1, Land Corner records, Houghton County. Another position, 927.4' north of that described here was monumented in 1994 and recorded as 19 in 1995 by C.E. Hein RLS 13034, Vol 3, Pg. 243, Houghton County. (Continued on back of this sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The original post and accessories were not recovered. Recovered a 1" ID iron pipe, firmly set, projecting about 12", with a 2" ID iron pipe driven over it. The 2" IP has rotted off near ground level and is not firmly set. Recovered the 1984 witnesses as follows: 12" Y. Birch (long dead) N82E 13.5' (this is also the Larsen witness), 12" Sugar N44W 12.6' to center, 18" Sugar S16E 11.5' to center (magnetic brgs.). The 1984 N82E and S24E witnesses seem to be transposed on the LCRC. I recovered an old iron pipe at the current S. shore of Lake Roland which, by measurement, and description appears to be that noted by Larsen at 1.90 ch. South of the MC. I verify the position of R.A. Mick's pipe at 19 by measurement and reference to the original record noted above: 5) 19.7 M, 6) 24.25 M, 8) 31.77 ch. (to find pipe) + 1.90 ch. (meas. by M.C. Larsen) = 33.67 ch. 11) 42.37 M, 12) 7.6 M, 13) & 14) 12.44 M to old cedar stump and E'ly edge of low wet land. Stump is hollow, burnt, and 18" dia. with no markings visible, 15) 81.82 M. The original notes make no mention of a lake crossing along the line between Sections 22-27. (Continued on back of this sheet)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1" pipe with 4" MDNR cap. Blazed and scribed the following:

16" Sugar S18E 10.8' "S26 NBT"

8" Maple S50W 21.0' "S27 NBT"

10" Sugar N43W 12.3' "S22 NBT"

12" Y. Birch N83E 17.6' "S23 NBT"

Placed the 2" ID and 1" ID pipes

adjacent. Bearings are magnetic.

Distances are to measuring notch in

lower blaze.



Signed by

Surveyor's Michigan License No.

33986

Date

4-6-99

For the Michigan Department of Natural Resources - Forest Management Division