APPROVED LAND CORNER P.A. 345 OF 1990 Houghton County

Max.	6, 19	98	
كاملاب	i W.	Cample	>

	county										
Roy 6	1998	LAND	CORNER R	ECORDATION C	ERTIFICATE	[-ζ] -ππ.	از الارادي الا الارادية الارادية الارادية	1 19 mg / 10 m			
_viauci	U. Ceon	Filing	g Requiremer	nt of Act 74, Mich	n. P.A. 1970	ه قالعنو	કેઇ કે માત્ર કે <u>ડ્રિ</u>	وأتعالمه	ي لا لا سا	73 C	الاراج العدا و المراد الرحية
For corner <u>HO</u>	s in <i>UGHTON</i> (County)	Located In:		Corner Code #	l		DEC	14	199	\$	
					1		- Th				
1. Public	Land Survey	т <i>53W</i>	R <u>33W</u> R <u>33W</u> R (MEANDER-7 MEANDER-6	_ Seg.1		وی است در این این در این این	GTK	M		
		т	R		ROBERT F.			11/	16/	98	
	ty Controlling	S T			нопентой с	OUNTY.	, RE	31S7	ER		
in Section 3. Miscel		S T S T			_C 3/	543 P	Pag:		1 0		. Ø 1
	ty in Section	=:					 		1 0	1	Ţ
4. Lot No)	, Recorded Plat				A B	DE	FO	а н	<u>1</u> J	ĸ
5. Private	Claims					2 6			_3-		
					*	3		1	_Ľ		
						4 - 7 -		9	— 10	 —11-	
R.V	V. CRAMPTOI	Y, in a field survey on _	00	CTOBER 30 , 19	<u>98</u> ,	5		_	_ -	 	-
do hereby d	certify that under	r requirements of P.A. 74, N	/lichigan P.A. of 1	1970, the corner points	s mentioned	6 - 18	17	16	—15—	14-	+
in lines 1 ar	d 2 above were	in conformance with regulations of the United State	ations and rules t es Department (neretore as required in of the Interior, Burea	n the current au of Land	7				╂─┼	+
Manageme	nt or by a decre	e of a Court of Law and/or	that the corner	points mentioned in lir	nes 3, 4 and	8 19	-20	—21·	—22·	-23	
5 above we	ere in conforma	nce with the rules of the feestablished, re-established,	Michigan Board o	of Professional Survey	ors or by a	9	\dashv			╂┈┼	+
as expresse		established, refestablished	, monamented, i	e-monumented, 1900v	rerea, rouria	10 -30-	-2g	—28-—	2 ¹ 7	26	+
-		corners, all in the same	town and rang	ge, may be recorded	d	11			-	†++	
	n this certificat		_			12 31	32 	—₃i₃— I	34 I	35-	+
A. Desci	ription of origi	nal monument and acc	essories and/o	r subsequent resto	ration:	131				-LL-	
ME ME	ANDER-7, S ANDER-6, S	SET MEANDER POST (SET MEANDER POST (ON LEFT BANI ON RIGHT BAI	K (NO WITNESSES) NK, NO TREES FOI) R BEARING						
	•	ner evidence found and					רנגע פ	SW C	ORNE	'D	
Mi		SET 1 1/4" IRON PIPE OF SECTION 2, 50' FR S89°53'44"E 1600.60'	OM THE WAT	ER'S EDGE OF PO	ORTAGE CANAL	ON THE	WEST.	BANK	,	.A.L	
M	3	SET 1 1/4" IRON PIPE WEST SECTION LINE (EDGE OF PORTAGE C	OF SECTION 2	AND THE SW COL	RNER OF SECTI	ON 2, 10	o' FRO	M WA	TER'	S	
	EANDER-7,	nument for corner and a THE 1 1/4" IRON PIPE	Z WITH BRASS	CAP WAS WITNES	SSED WITH SUR						
		10" SPRUCE TREE N8 14" W. BIRCH TREE S	28°W 164.82',	14" W. BIRCH TR	EE S59°W 187.5						
M	EANDER-6,	THE 1 1/4" IRON PIPI	E WITH BRASS	CAP WAS WITNES	SSED WITH SUR	VEY TAG	NAILI	ED TO	:		
		12" W. BIRCH TREE N 12" W. BIRCH TREE S	161°W 19.72', 28°W 20.10', .	8" W. BIRCH TREI 14" W. BIRCH TRE	E N02°W 31.46', EE S62°W 22.58'	•	25	of	MICH	O COLOR	

Signed by_ Surveyor's Michigan License No. 24591 PORM APPROVED BY MICHIGAN STATE BOATE OF THOSE SIGNAL SURVEYORS (M. 26/1971) 1975

SONAL SPRINGER AND, 1983

ROBERT W.
CRAMPTON
LAND
SURVEYOR
NO.