

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County) Located In: Corner Code #
1. Public Land Survey T R
2. Property Controlling in Section S 36 T 53N R 35W 15 (GCDB 620100)
3. Miscellaneous Property in Sec. S 36 T 53N R 35W 11 (GCDB 620120)
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 11 10/07/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 36) West 1/16 corner on the south line of Section 36. Not a common 1/16 corner with Section 1, T52N-R35W. Not previously monumented.

(11-Sec. 36) Southwest 1/16 corner, Section 36. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 36) Established the position for the corner midway and on the Township line between Section corner 1329.55' west and Quarter corner 1329.55' east. The monument leans west about 0.1' due to rock. The top center of the cap marks the corner position.

(11-Sec. 36) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the east and south being monumented.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 13" Sugar N07°W 11.3' mrkd "1/16S BT" 14" Sugar S57°E 21.4' do 4" Poplar S12°E 10.25' do 5" Sugar N64°W 7.65' do Set sq'd cedar post adjacent. E= 7870962.488 N= 240942.018

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 9" Cedar N23°E 11.5' mrkd "1/16S BT" 5" Cedar S59°E 15.1' do 5" Cedar S07°W 10.35' do 6" Cedar N24°W 7.8' do Sq'd a 3" balsam S30E 1.9' for a post. E= 7870976.977 N= 241339.623

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by [Signature] Date 11/04/2015 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division