

DEC 14 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton
(County)

Located in:

Corner Code #

1

1. Public Land Survey

T 54N R 33W

T 54N R 33W

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

ROBERT F. MIKESCH 11/11/98
HOUGHTON COUNTY, REGISTER 09:40
LC 3/ 517 PAU Fee: 9.00
Page 1 of 1

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Ronald S. Haataja, in a field survey on August 13, 19 98,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J-7) S 1/4 Corner Section 14, T54N-R33W
40.00 Set Quarter Section post
Witnesses: Sugar 12" S56°E 20 lks.
Yellow Birch 9" N16°W 7 lks.

(Z14) Meander Corner between Sections 14 & 23, T54N-R33W
74.80 Intersected Lake
Cedar 4" for Meander Corner
Witnesses: White Pine 16" N48°E 13 lks.
Do 18" S28°W 27 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J-7) S 1/4 Corner Section 14, T54N-R33W
Found 3/4" Iron pin w/ flange at top according
to LCRC Liber 2, Page 475

(Z14) Meander Corner between Sections 14 & 23, T54N-R33W
Found 1" Drill rod in concrete according to
LCRC Liber 2, Page 479. Located in front lawn of camp
with fire # 314

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J-7) S 1/4 Corner Section 14, T54N-R33W
Drove 2" Aluminum pipe over pin and stamped and cemented a
brass remon. cap into pipe. Witnesses: Brass tags PS#39478
nailed into side of trees: 9" Balsam N08°W 4.75', 8" W. Birch
S73°E 45.39', 4" Maple S24°W 3.89', 7" Maple N87°W 10.05',
Fence line to North and South

(Z14) Meander Corner between Sections 14 & 23, T54N-R33W
Drove drill rod down and stamped and cemented a brass remon.
cap inside an 8" iron liner. Witnesses: Brass tags PS#39478
nailed to trees: NE Cor Hse S85°E 23.25', NW Cor Hse South
18.13', 12" Oak S77°W 16.75', 14" Maple N09°E 8.13',
15' to water's edge.

Signed by Ronald S. Haataja

Date November 6, 1998

Surveyor's Michigan License No. 39478

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	6	5	4	3	2	1					
5												
6	16	17	18	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

