

DEC 14 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Houghton  
(County)

Located in:

Corner Code #

ROBERT F. MIKESCH 11/11/98  
HOUGHTON COUNTY, REGISTER 09:40  
LC 3/ 516 PAU Fee: 9.00  
Page 1 of 1

1. Public Land Survey T 54N R 33W  
T 54N R 33W  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

I-8  
Z15

#3

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Ronald S. Haataja a field survey on April 15, 19 98,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (I-8) E 1/4 Corner Section 22, T54N-R33W  
40.00 Set Quarter Section post  
Witnesses: Hemlock 14" N24°W 7 lks.  
Yellow Birch 28" S71°E 27 lks.

- (Z15) Meander Corner between Sections 22 & 23, T54N-R33W  
71.96 Intersected Portage Lake, Set Meander Corner post  
Witnesses: Yellow Birch 14" S11°W 27 lks.  
Fir 8" S46°E 15 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (I-8) E 1/4 Corner Section 22, T54N-R33W  
Found 1 1/2" pipe according to survey by H. Lawrence  
O'Donnell dated 12/11/86, and LCRC Liber 2, Page 477

- (Z15) Meander Corner between Sections 22 & 23, T54N-R33W  
Found 3/4" Capped pipe PS#19833

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- (I-8) E 1/4 Corner Section 22, T54N-R33W  
Stamped and cemented a brass remon. cap into pipe  
Witnesses: Brass tags PS#39478 nailed into side of trees  
5" Maple N73°E 14.35', 14" Maple S28°W 27.32',  
8" Maple S75°W 25.07', 9" Maple N34°W 11.80'.  
(Z15) Meander Corner between Sections 22 & 23, T54N-R33W  
Drove 2" Aluminum pipe over capped pipe and stamped and  
cemented a brass remon. cap into 2" pipe  
Witnesses: Brass tags PS#39478 nailed into side of trees  
7" W. Pine N35°W 4.70', 5" Maple S11°W 15.42', 12" Oak  
S75°E 35.13', 3" Oak N55°E 16.28', 40' North to water's edge

Signed by Ronald S. Haataja

Date November 6, 1998

Surveyor's Michigan License No. 39478

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

