REMONUMENTATION

JUL 2 3 1999

SECTION

Service /

APPROVED LAND CORNER FLATTER OF THE HOURTON COUNTY

Rolet W. Camps

By: Hitch, Inc., P.C., Houghton, MI Job No. 97012

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in		MARY SCHOOS	05/05/	39	2			
<u>}</u>	loughton County Located In:	Corner Code #	HOUGHTON COU LC 3/59	p PHU Fee	: 9.	00			
1.	Public Land Survey Section 31 T_55N R_32W T R T R T R	B, C-13 # 2 (Meander Corner)	1	Page	1 of	1			
3.	Property Controlling S T R in Section S T R Miscellaneous S T R Property in Sec. S T R				egister of	Deeds S	tamp &	Fli o	7
	Lot No, Recorded Plat Private Claims				,		o T		
	Corner B, C-13 is the meander corner on the E. shore o (also Township line) common to Section 31, T55N, R3			1 B	S	4	3	2	1
sta 1 a ma Ma 5 a	Michael T. Drewyor , in a field survey on De te that under requirements of P.A. 74, Michigan P.A. of 1970, and 2 above were in conformance with regulations and rules unal of survey instructions of the United States Departmenagement or by a decree of a Court of Law and for that the combove were in conformance with the rules of the Michigan Boals Court of Law; established, re-established, monumented, reco	the corner points mention therefore as required in the of the Interior, Bure there points mentioned in line and of Land Surveyors or	oned in lines the current au of Land nes 3, 4 and by a Decree	5 - 18 7 - 19	17	9	15 1	3 2	12
NC	TE: Not more than 2 corners, all in the same town an on this certificate.	nd range, may be reco	rded	1 30	29	28	27 2	6	25
Α.	Description of original monument and accessories and	lor subsequent restora	ation:	1231	32	33	34 :	5	36
	Meander Corner - At 74.75 chains (meas. Trigonome coast S4E & N15E, set meander post.	trically from W), cours	se of		rner B			<u> </u>	<u>L</u>
	White Pine 28, S 11° E, 21			- ME	ander /	corner.	₩ ∠ ±		
	No evidence of original monument or accessories four July 13, 1845 & July 24, 1845.	nd. This line was origi	nally surveye	d by Dep	uty Surve	eyor Willi	am Ives	bet we	en
В.	Description of corner evidence found and/or method a	pplied in restoring or r	eestablishing	comer:					
	Meander Corner - In 1967, Charles Hein, RLS 13034 Section 31. I retraced Chuck's survey & found the m bent Southerly. This corner is located on the West sign	leander corner as calle	d for. Found	1" solid	iran rod 7	st of the	SE corr grade, i	ner of ron rod	i.
C.	Description of monument for corner and accessories ex	stablished to perpetua	te locating the	position	of the c	orner:			
	All witness points in trees are PK nails and washer	īs.	maria dimen						
v	Meander Corner - Found 1" iron rod (description a	above).	TORK						
	Witnesses:		1	S.	e Arger				as y.
	N 79° E, 24.80 ft., 25" White Pine S 58° E, 16.79 ft., 7" Cedar S 34° W, 16.27 ft., 17" White Pine N 74° E, 32.49 ft., NW House Corner S 24° E, 49.85 ft, SW Rouse Corner			anne (
Q;	aned by Mullium J. Mullium		United Town Society	ate	April 13	. 1999			
	riveyor's Michigan License No. 24245				* *DIA 15				_
_		FORM APPR	OVED BY MICHIGA	IN STATE BO	ARD OF PRO	FESSIONAL S	URVEYOR	, JAN. 28	3, 1971
		.*					REV	MAY 14 ISED JAN SED OCT.	., 1983