

JAN 19 2001

2000 REMONUMENTATION

Re-Mon. Liber 2, Page 73

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

STATE OF MICHIGAN  
HURON COUNTY  
RECORDED

20 SEP 2000 2:05 PM

FRANCES L. HOLLOWICK  
REGISTER OF DEEDS

<u>Huron</u>	Located in:	Corner Code #
(County)		
1. Public Land Survey Sand Beach	T16N R16E	A-11
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
In Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Charles S. Getz, in a field survey on July 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5			4		3		2		1
3												
4	7		8			9		10		11		12
5												
6	18		17			16		15		14		13
7												
8	19		20			21		22		23		24
9												
10	30		29			28		27		26		25
11												
12	31		32			33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

A-11 1834 G.L.O., H. Parke D.S. County Road Commission Records - Iron Rod  
Set Post  
Fir 6", S10°W, 7 Links Recorded Surveys - Case, 6-29-76, Liber 2, Page 651, 3/4" Iron Pi  
Hemlock 6", N46½°W, 17 Links Unrecorded Surveys - Case, 1-21-91, Certificate shows Corner

L.C.R.C. - NONE


County Surveyor Records -  
NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11  
SW Cor, Section 30, T16N-R16E  
Found 3/4" Iron Bar  
Accepted as the best available evidence  
of the original corner position  
(Intersection of Toppin Road & Edwards Road)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11  
SW Cor, Section 30, T16N-R16E  
Found 3/4" Iron Bar  
S45°W 52.7' to Nail in Fence Post  
N45°E 46.52' to Center of 12" Conc. Post  
S45°E 40.50' to Stop and Road Sign Post  
N45°W 36.25' to Stop and Road Sign Post  
N50°E 72.0' to Nail in Power Pole  
North 2601.80' to W 1/4 Cor, Sec 30, T16N-R16E  
South 2617.20' to W 1/4 Cor, Sec 31, T16N-R16E



Signed by Charles S. Getz  
Surveyor's Michigan License No. 25843

Date July 23, 2000

PEER GROUP APPROVED AT MEETING  
HELD September 18, 2000. RAB