

ACCEPTED BY THE HILLSDALE COUNTY  
SURVEY REEVALUATION GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT 348  
1990 AT A MEETING HELD ON  
-28-94  
AL RINGENBERG, CO. REP.

LIBER 3 PAGE 79  
REMONUMENTATION

RECORDED  
HILLSDALE CO. MICH.  
97917  
'94 DEC 14 AM 11 59

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Judy VanZandt  
REG. OF DEEDS

For corners in

HILLSDALE  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 5S R 1W

G1, G2,

2. Property Controlling  
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

SURVEY &  
REMONUMENTATION

APR 27 1995

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

COMMISSION

I, John E. Maxson, in a field survey on 4 November 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-1  
GLO, 1824, 6"W.Oak, N47E, 16 lks  
6"W.Oak, S52W, 16 lks  
Standard Corner West, 262 lks  
Geo. Mark, 1885, No. 998  
No Object

G-2  
GLO, 1824, 8"B.Oak, S09W, 66 lks  
10"B.Oak, S64.5E, 62 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-1  
Set Corner from Plat of "CHERRY PARK NO. 2" and accepted as the best available evidence of the position of the original Corner

G-2  
Found capped iron that fits the Plat of "CHERRY PARK" and accepted as the best available evidence of the position of the original Corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-1  
Set 5/8 x 36 rebar w/cap  
N68W 78.83' 30"Walnut  
N15W 36.67' 10"Db1.Locust  
N47E 68.78' SW Cor. Hse. #1290  
S01W 39.37' Iron at NE Cor Lot 498  
West 178.05 Con. Mon.  
G-13, T4S-R1W

G-2  
Reset 5/8 x 36 rebar w/cap  
S45W 33.09' 14"Oak  
South 31.40' 8"Tw.Oak  
S82E 15.59' 6"Cherry  
N82E 29.64' 8"Oak



Signed by John E. Maxson  
Surveyor's Michigan License No. 27454

Date 12 December, 1994