197:1

LIBER 3 PAGE 206

HILLSDALE COUNTY REMONUMENTATION CORNER 97 NOV 3 PM 4 19 LAND CORNER RECORDATION CERTIFICATE

18 ⁶ 17 184 :	Filing Requirement of	Act 74, Mich. P.A. 1	970 🔿	1 1	5
For corners in		J	<i></i>	July Von	Joungs -
_ HILLSDALE	Located In:	Corner		REG. OF DEE	DŠ
Code #		Conton			
(County)			S	SURVEY &	
ALLEN TWP. Public Land Survey	TG S D A M			NUMENTATION	ON
, rubiic Laild Survey	T <u>6 S R 4 W G-11</u> TR				
A Comment of the Comm	TR		F	EB 1 1 1998	
dig.	T R				
2. Property Controlling	S TR		\$	BECTION	
in Section 3. Miscellaneous	S TR		Register	r of Deeds Stamp 8	& File Number
Property in Sec.	S T R				
				•	
4 Lot No, Rec	orded Plat		A B C	DEFGH	IJKLM
5 Private Claims			2 6	-5-4-3-	
			3		
**************************************			4 7	- B910-	11-12
I, <u>EDWARD W. REED</u>	, in a field survey on <u>OCT</u>	<u>DBER 6 ,</u> 19 <u>97</u> do	5		
lines 1 and 2 above were in cor	ments of P.A. 74, Michigan P.A. of 1970, the corn of a mance with regulations and rules therefore as	ner points mentioned in	6 18	-17 16 15-	14 13
manual of survey instructions	s of the United States Department of the Int	erior. Bureau of Land	7		
Management or by a decree of 5 above were in conformance v	a Court of Law and /or that the corner points me with the rules of the Michigan Board of Land Surv	ntioned in lines 3, 4 and	8 -19	_202122_	23 24
a Court of Law; established, re-	established, monumented, recovered, found as e	cpressed below:	9		
NOTE: Not more than 2 co	orners all in the same town and some ways	h	10 30	-2 9 -2 0 27	26 25
on this certificate.	orners, all in the same town and range, may	pe recorded	11		
4			12 31	32 33 34	35 36
the same of the sa			13		
A: Description of original n	monument and accessories and/or subsequ) SECTIONS 27-28-33-34	ent restoration:			
SOUTH COMMON TO	7 SECTIONS 21-20-33-34				
NO INFORMATION AVA	AILABLE SINCE GLO				
B. Description of corner e	vidence found and/or method applied in res	storing or reestablishing	g comer:		
FOUND 1/2 IRON WITH I	FLAGGING ON NORTH SIDE OF LAR	GE STONE	•		
* p	RON WITH REMON CAP IN CI-MON	JMENT BOX 4" BEL	.OW GRAV	EL ROAD SURI	FACE
C. Description of monur	ment for corner and accessories establishe	d to perpetuate locating	g the position	of the corner:	
IN LINE WITH FENCES	RUNNING NORTH & SOUTH	. St. Sandarder	A CONTRACTOR OF THE PARTY OF TH		
SW CORNER HOUSE, N		ر پیر را جمعی این این این این این این این این این ای			
FACE OF LARGE STON			•		
	DE 24" MAPLE, S85W 110.54' DE 18" TWIN BUTTERNUT, N61W 67.4	In S			
	DE 24" WALNUT, SOUTH 38.71'	5			
				t Capit	
AND IS ACCEPTED AS	A CAREFUL AND FAITHFUL PERPET	UATION OF THE P	OSITION O	F THE ORIGINA	AL CORNER
	- /1				
Signed by Jane	W. Kul		Date	OCTORED 6	1007
	DEED.		Date	OCTOBER 6	. 1991
EDWARD W. R					
Suprever's Michigan Lice	2200E				