



RECORDED
HILLSDALE CO. MICH.

00 NOV 13 AM 11:09

Judy VanJanet
REG. OF DEEDS

HILLSDALE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE Located in: Corner Code #
(County)
PITTSFORD TWP.

1. Public Land Survey T7S R1W I-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Frederick J. Cutcher, in a field survey on Oct. 22, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., 1824: Set Post; Beech 18" N. 79° W. 14 lks.; Beech 5" N. 10-1/2° E. 13 lks.
Survey #467, June 1867, Geo. Mark: Stone.
LCRC L. 2, P. 68, Oct. 8, 1885, Glenn Richard, P.S. #13040: Found R. R. Spike in monument box very deep. Raised to surface with 3/4" iron pipe; P.K. in 48" Maple N. 20° W. 77.66'; P.K. in Tel. Pole N. 40° E. 70.23'; Nail and disc in Tel. Pole S. 20° E. 64.83'; Cen. of C.B. N. 50° W. 51.50'.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" iron pipe in monument box at road surface in centerline intersection of M-34 and Nye Road. References in LCRC remain and check.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation cap on 3/4" iron pipe in monument box and is accepted as the best available evidence of the position of the original corner.
in centerline intersection of M-34 and Nye Road.
Top cen. tel. stan. N. 45° E. 69.0'
Top cen. tel. stan. S. 23° E. 64.23'
Nail & spotter 24" Maple N. 10° W. 112.65'
Cen. Blue Spruce N. 47° W. 79.55'



Signed by *Frederick J. Cutcher* Date 11/9/2000
Surveyor's Michigan License No. 24592